











Key

-  Category A - trees of high quality and value
-  Category B - trees of moderate quality and value
-  Category C - trees of low quality and value
-  Category U - trees of unsuitable for retention
-  Tree is not identified on TOPO, therefore, location of the tree is not accurate
-  Group of trees / hedge
-  Root protection area
-  Trees to be removed
-  Tree protective barriers
-  Construction Exclusion Zone - area requiring a special consideration - refer to report

Please note that this plan is not based on a topographical survey and has been plotted by hand, therefore, the location of the trees must be checked on site.

This drawing was produced in colour - a monochrome copy should not be relied upon. Contractors must check all dimensions on site. Any discrepancies must be reported to the arboricultural consultant before proceeding. ©SES 2016.



Sudbury Stables Downham,
Essex CM11 1LB

Phone: 01268 711021
Website: www.ses-eco.co.uk


Rev	Update	Date
-		

Site
10 Downside Crescent, London

Client
C/O Bowtie Construction Ltd

Drawing title
Tree Survey & Protection Plan

Drawing no. 1	Scale 1:200@A3	Date 27.07.16
------------------	-------------------	------------------

Revision -	Drawn by AD	Orientation 
---------------	----------------	--