

Tree Aware UK Ltd
Company Reg 08330676
Email enquiries@treeawareuk.com

BS 5837: 2012 Tree Survey

11 Buckland Crescent, London

Undertaken by Alastair Gavin on behalf of Tree Aware UK Ltd on the 05/10/2016

[This document sets out to evaluate the trees surveyed on the 05/10/2016 in accordance to BS 5837:2012 "Trees in relation to design demolition and construction" this document is not a tree condition survey it categorizes the tree or trees based on their quality and value and thus allows for an informed decision to made in respect to the tree/trees retention and removal in connection to development.]

Methodology

This survey has been undertaken in compliance with BS 5837: 2012. This survey is not a tree condition survey; none of the trees have been climbed nor has any decay detection equipment been used, any comments in connection to the trees condition are incidental and secondary in nature, the main objective of this survey is to inform and guide decisions in connection to development.

Where hazardous trees have been identified and recommendations given for immediate action, this should been undertaken and arranged as soon as possible.

<u>Sequential Reference Number</u>

All trees surveyed have been given a sequential reference number such as T1, T2, T3 Etc where trees form a group (which is decided by the surveying Arboriculturalist) a group reference number will be provided these will be in the line of G1, G2, G3 etc.

<u>Species</u>

The tree species will be listed in the schedule by their common name a key to their scientific names can be found below;

Tree Reference number	Common Name	Scientific Name	Native/None native
T1	Lilac Bush	Syringa	None Native
T2	False Acacia	Robinia pseudoacacia	None Native
T3	False Acacia	Robinia pseudoacacia	None Native
T4	Horse Chestnut	Aesculus hippocastanum	None Native
T5	Lime	Tilia cordata	Native

Tree Height

Tree height has been taken in meters and is an approximate measurement.

Diameter of Stem

The diameter of a single stem is taken at 1.5m above ground level. Where there are multiply stems arising from either the base of the tree or below 1.5m the diameter of the stem is calculated using annex C in the British standard BS 5837: 2012 handbook.

Crown Spread

_		•				•		•	1. 1	
	\mathbf{h}		measured	110	matara	LICINA	+ 12 12	+0116	COKMINOI	naintei
			111647111611		1110101		1110	11111	(altilla)	11/11/11/
	1113	13	IIICasai ca		111000	UJIII	LIIC	IOUI	cai airiai	DOIIILD.

North

South

East

West

Height of first branch

Approximate height in meters of the first significant branch a cardinal point maybe given to indicate the direction the branch is growing in.

Canopy Height

Approximate height of the canopy taken in meters

Life Stage

The trees are classified into the following life stages dependant on their age. The category's are;

Young

Semi-mature

Early mature

Mature

Over mature

General Observations

The tree/trees are observed for any structural or physiological conditions such as the presence of decay, structural defects, pest and disease pathogens etc any such identification will be noted and preliminary management recommendations made.

Estimated remaining contribution, in years

Based on the trees condition an estimate on the remaining useful life expectancy of the tree/trees is given these will be in the following category's

Under 10 years

10+

20+

40+

BS 5837 Category

Category A, B, C or U is given to the trees based on the below criteria.

The purpose of the categorization which is undertaken by the surveying Arboriculturalist is to identify the value (in a none fiscal sense) and the quality of the tree stock on site so that informed decisions can be made in regards to what trees should be removed or retained in connection to development.

Category A, B, C trees are considered worthy of retention where category U trees are generally considered unworthy for retention but may have conservation value which may be desirable to conserve.

Category A

Trees of high quality with an estimated remaining life expectancy of at least 40 years.

(Having one or more of the following qualities)

1 . Mainly arboricultural qualities

Trees that are particularly good examples of their species, especially if rare or unusual; or those that are essential components of groups or formal or semi-formal arboricultural features (e.g. the dominant and/or principal trees within an avenue)

2. Mainly landscape qualities

Trees, groups or woodlands of particular visual importance as arboricultural and/or landscape features

3. Mainly cultural values, including conservation

Trees, groups or woodlands of significant conservation, historical, commemorative or other value (e.g. veteran trees or wood-pasture)

Category B

Trees of moderate quality with an estimated remaining life expectancy of at least 20 years

(Having one or more of the following qualities)

1 .Mainly arboricultural qualities

Trees that might be included in category A, but are downgraded because of impaired condition (e.g. presence of significant though remediable defects, including unsympathetic past management and storm damage), such that they are unlikely to be suitable for retention for beyond 40 years; or trees lacking the special quality necessary to merit the category A designation

2. Mainly landscape qualities

Trees present in numbers, usually growing as groups or woodlands, such that they attract a higher collective rating than they might as individuals; or trees occurring as collectives but situated so as to make little visual contribution to the wider locality

3 Mainly cultural values, including conservation

Trees with material conservation or other cultural value

Category C

Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150 mm

(Having one or more of the following qualities)

1. Mainly arboricultural qualities

Unremarkable trees of very limited merit or such impaired condition that they do not qualify in higher categories

2. Mainly landscape qualities

Trees present in groups or woodlands, but without this conferring on them significantly greater collective landscape value; and/or trees offering low or only temporary/transient landscape benefits

3. Mainly cultural values, including conservation

Trees with no material conservation or other cultural value

Category U

Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use for longer than 10 years

- Trees that have a serious, irremediable, structural defect, such that their early loss is expected due to collapse, including those that will become unviable after removal of other category U trees (e.g. where, for whatever reason, the loss of companion shelter cannot be mitigated by pruning)
- Trees that are dead or are showing signs of significant, immediate, and irreversible overall decline.
- Trees infected with pathogens of significance to the health and/or safety of other trees nearby, or very low quality trees suppressing adjacent trees of better quality.

Groups of trees and woodlands

Where groups of trees or woodlands exist on the site it is down to the surveying Arboriculturalist to designate these features and to decide on what information

should be recorded in respect to these. In certain circumstances individual trees within a group or woodland are surveyed individually, such as when there is a need to differentiate between them e.g. when variation is present in their structural condition.

Hedgerows, substantial internal or boundary hedges (including evergreen screens)

These are surveyed similarly to groups of trees with the lateral spread and average height and stem diameter ranges recorded. All woody species present on the site are recorded; this is to allow the potential constraints associated with such features to be fully assessed.

Where accurate measurements cannot be gained due to inaccessible trees a # will be put at the end of the figure indicating it is an estimate.

Tree Survey Schedule

Sequential Reference Number	Species (Common Name)	Height	Stem Diameter	Branch Spread N S E W in meters	First Significant Branch	Canopy Height	Life Stage	General Observations	Estimated Remaining Contribution in years	BS 5837 Category
T1	Lilac Bush	4m	080mm 060mm 050mm 080mm	2, 1, 1, 2	Ground Level	30cm	Mature	Multi stemmed large Lilac bush with an average to poor form, evidence of past branch pruning, tree shows signs of good vitality, dead wood in canopy, suppressed by neighbouring vegetation.	10+	С
T2	False Acacia	4m	080mm 050mm 050mm	2, 2, 2, 2	Ground Level	1.90m	Juvenile	Multi stemmed tree being potential suckers off an original tree, average to poor form, tree shows signs of good vitality, dead wood in canopy evidence of past reduction to stems, re-growths present.	10+	С
ТЗ	False Acacia	11m	650mm	3#, 4, 3, 3	3m	4m	Mature	Bark death to stem north side, decay likely to be present in stem, tree previously reduced with regrowths present, tree in an average to poor condition, Ivy on stem impeding a full inspection from taking place. Tree potentially pollarded in the past and allowed to re-grow.	10+	С

								Recommendation Remove Ivy and monitor condition of tree		
T4	Horse Chestnut	15m	720mm#	5, 5, 4, 4	3m	1.5m	Mature	Ivy on stem of tree as such tree could not be fully inspected, tree suffering with leaf minor infestation, tree significantly pollarded in the past reason unknown, re-growths present, tree further reduced by 20% tree has a good form. Recommendation Remove Ivy and reduce tree ever 3-5 years, monitor condition of tree.	20+	В
T5	Lime	15m	440mm#	2, 4, 3, 4	3m	2m	Mature	Tree suppressed by T4, one sided canopy favouring the south west side, could not fully inspect tree due to tree being located in neighbours garden and restricted access, dead wood in canopy, lvy on stem of tree, tree appears to be in an average condition. Recommendation Remove Ivy and dead wood	20+	В

Root Protection/Constraint Plan

(Please see separate document)