

Ref: 216177  
Project: 43-45 Bedford Square  
Title: No. 43 Cantilever Stone Staircase Newel  
Post Remedial Details



**Methodology for Repairing Newel  
Post Base Fixing:**

1. Carefully remove existing lead caulking by continuously drilling out around base of newel post.
2. Replace with SBD Epoxy Plus low viscosity resin leaving 4mm recess.
3. Fill recess with soft lead shavings carefully heated with fine jewelry maker's blowlamp to match original detail.

Location where repair is to be carried out.