# Appendix A Desk Study Information

## Library Search Results

Map 1: Street Map

Map 2: Old Ordnance Survey Map 1879

Map 3: Old Ordnance Survey Map 1896

Map 4: Old Ordnance Survey Map 1915

Map 5: Old Ordnance Survey Map 1934

Map 6: Old Ordnance Survey Map 1953-1955


Map 7: Geological Survey Map

Map 8: Bomb Damage Map


Map 9: Lost Rivers of London Map

Map 10: Tube Map






Map 1: Street Map




Map 2: Ordnance Survey Map Year 1879



Map 3: Ordnance Survey Map Year 1896




Map 4: Ordnance Survey Map Year 1915




Map 5: Ordnance Survey Map Year 1934







Map 6: Ordnance Survey Map Year 1953-1955

### 26 Christchurch Hill



Map 7: Geological Survey Map





Map 8: Bomb Damage Map

#### Colour Key References

(for guidance only)

#### Black Total

destruction

#### Purple

Damaged beyond repair

#### Dark Red

Seriously damaged; doubtful if repairable

#### Light Red

Seriously damaged, but repairable at cost

#### Orange

General blast damage – not structural

#### Yellow

Blast damage, minor in nature

#### Light Blue Clearance

Clearance areas

#### Light Green

Clearance areas




V1 flying bomb




V2 long range rocket





Map 9: Lost Rivers of London Map



Map 10: Tube Map