
Sample Window Conditions

Melia White House Hotel

Condition of Windows Sample

Melia White House Hotel



Window Sample 01 - Frame rotten / closing mechanism broken – Not repairable



Window Sample 02 – Frame rotten / warped frame / not possible to close – Not repairable

Condition of Windows Sample

Melia White House Hotel



Window Sample 03 – Frame corroded away from frame / not possible to close – Not repairable



Window Sample 04 – Warped frame / not possible to close – Not repairable

Condition of Windows Sample

Melia White House Hotel



Window Sample 05 – Rotten frame / corrosion of hinges / not possible to close – Not repairable

Condition of Windows Sample

Melia White House Hotel



Window Sample 06 – Rotten frame / warped frame / not possible to close – Not repairable

Condition of Windows Sample

Melia White House Hotel



Window Sample 07 – Rotten frame / warped frame / not possible to close – Not repairable

Condition of Windows Sample

Melia White House Hotel



Window Sample 08 – Rotten frame / warped frame / not possible to close – Not repairable