







NOTES:		REVISIONS			Client:		- i - " - : i -	5
1 Pipes crank around cornice	17) Poor detailing resulting in weather staining	No Date	Issue For	Issue By	Michael and Kelly Pawlyn	CX	CXCICICIC	Ĭ
		00 31-03-17	31-03-17 Plan. submission	MP				
2 Poor quality lintels	(18) Poor quality gates					Third Floor, 28-42 Banner Street, Lon	Third Floor, 28-42 Banner Street, London, EC1Y 8QE Office + 44 (0) 2072518088	1 Y 8 Q E
(3) Central windows inconsistent with historic precedent	19 New white painted render				Project: Prove End House	Info@exploration-architecture.com	-architecture.com	
8 Pipes removed	20 Improved detailing					www.explora	www.exploration-architecture.com	com
(10) New brick arches to match those below	(21) New gates							
12 New central windows to reflect historic precedent	(Title: Existing and proposed front views	Drawn: Chk: F	Project Number: 1502	
16 Poor quality cement render					-	Scale:	Dwg No: AR-005	Rev: