Cooke Fawcett Ltd

Rose Cottage CF-SCH-135-800

Window and external door schedule 30.06.2017

Revision C

Description	Existing	Proposed
Doors		
Ground floor bathroom	Timber framed, glass panelled door, fanlight above, paint finish	Refurbish if possible, or replace like for like.
Main entrance hallway	Timber framed, glass panelled door, paint finish	Refurbish if possible, or replace like for like.
Rear door ground reception	Timber framed, single window above, paint finish, security bars	Replace with new timber framed french doors to match fenestration of neighbouring kitchen windows
Front door ground reception	Gothic style, timber framed, glazed doors, paint finish, internal sliding timber panelled pocket security shutters	Doors and shutters to be refurbished
Door to juliette balcony rear (1st floor)	Timber framed, glass panelled double doors, paint finish	Refurbish if possible, or replace like for like.
Door to main balcony (1st floor)	Timber framed, glass panelled double doors, fanlight above, paint finish	Refurbish if possible, or replace like for like.
Windows		
WC window	Timber framed, casement window	Refurbish if possible, or replace like for like.
Kitchen window	Timber framed, double casement window with solid timber panelling beneath	Refurbish if possible, or replace like for like. Timber panel to be replaced with masonry
Kitchen window	Timber framed, double casement window with solid timber panelling beneath	Window to be replaced with timber framed, double doors, fenestration to match existing arrangement
Window to rear of main reception room	Timber framed, casement window, leaded light fenestration	Refurbish if possible, or replace like for like.
1st floor landing	Timber framed, double casement window	Refurbish if possible, or replace like for like.
Rear bedroom 1	Timber framed, double casement window	Refurbish if possible, or replace like for like.
Rear bedroom 2	Timber framed, double casement window	Refurbish if possible, or replace like for like.
Rear bedroom 2	Timber framed, double casement window	Refurbish if possible, or replace like for like.
	Ground floor bathroom Main entrance hallway Rear door ground reception Front door ground reception Door to juliette balcony rear (1st floor) Door to main balcony (1st floor) Windows WC window Kitchen window Kitchen window Window to rear of main reception room 1st floor landing Rear bedroom 1 Rear bedroom 2	Doors Ground floor bathroom Timber framed, glass panelled door, fanlight above, paint finish Main entrance hallway Timber framed, glass panelled door, paint finish Rear door ground reception Timber framed, single window above, paint finish, security bars Front door ground reception Gothic style, timber framed, glass doors, paint finish, internal sliding timber panelled pocket security shutters Door to juliette balcony rear (1st floor) Timber framed, glass panelled double doors, paint finish Door to main balcony (1st floor) Timber framed, glass panelled double doors, fanlight above, paint finish Windows WC window Timber framed, dasement window Kitchen window Timber framed, double casement window with solid timber panelling beneath Window to rear of main reception room Timber framed, double casement window, leaded light fenestration 1st floor landing Timber framed, double casement window Rear bedroom 1 Timber framed, double casement window

135_SCH-0800_Windows_RevC