

172_23 Macklin Street
Appendix- Design and Access Statement
December 2013

Appendix A - Photographic Survey

Appendix B - Facade: Specialist Brickwork Façade Report

Appendix C - Pre-Application Feedback

Appendix D - Lifetime Homes

Appendix E - Schedule of Works

Appendix F - Photographs

Refer to the following reports for full information:

Structural Engineering Report



Services Report

Energy and Sustainability Report


Acoustic Report

Historic Report


Planning Report




Existing Internal View 1
Basement
Int. 01





Existing Internal View 2
Basement
Int. 01



Existing Internal View 2
Ground Floor
Int. 01



Existing Internal View 2
Ground Floor
Int. 01




Existing Internal View 2
Ground Floor
Int. 01



Ground Floor Swimming Pool (looking North) (A)



Ground Floor Swimming Pool underneath entry staircase (looking South) (B)




Existing Internal View 2
Ground Floor
Int. 01



First Floor Main Hall, view looking west (A)



First Floor Main Hall, view looking south-west (B)




Existing Internal View 2
First Floor
Int. 01



First Floor Balcony, view looking north (A)




First Floor Balcony, view looking south (B)



Existing Internal View 2
First Floor
Int. 01




Second Floor study looking south



Existing Internal View 2
Second Floor
Int. 01



Second Floor study internal balcony wing looking to the North and down into Main Hall



Existing Internal View 2
Second Floor
Int. 01