


Use only written dimension. All dimension must be verified prior to works being put into hand and any discrepancies reported to the originator.

DO NOT SCALE

Health and Safety Information

	Details	Sign	Date
Asbestos Survey			
Structural Check/Lifting & Handling			
Site Survey			
Access and Egress/Site Compound			
Hannada Islandifia si			

General Notes





29a Montague Street, London WC1B 5BL


Tel: +44(0)20 7636 2885 Fax: +44(0)20 7255 1729

6 Bayley Street London

Third Floor Plan

BB002 - 2017 - GA05 SEEM

A3 DRAFT



Unchanged Third Floor Scale 1:100