


NOTCH REPAIR DETAIL
FOR LONG NOTCH
 FOR NOTCHES GREATER THAN 25mm DEEP.



NOTCH REPAIR DETAIL 2
 FOR NOTCHES GREATER THAN 25mm DEEP.

DO NOT SCALE
 Use only written dimension. All dimension must be verified prior to works being put into hand and any discrepancies reported to the originator.

Health and Safety Information

	Details	Sign	Date
Asbestos Survey			
Structural Check/Lifting & Handling			
Site Survey			
Access and Egress/Site Compound			
Hazards Identified			

General Notes

REV	Details of Revision	Date	Sign



THE BEDFORD ESTATES

29a Montague Street, London WC1B 5BL
 Tel: +44(0)20 7636 2885
 Fax: +44(0)20 7255 1729

Project
 6 Bayley Street

Title
 Large Notch Repair

Drawing No
 BB002 - 2017 - DT03

Scale	Drawn	Checked	Co-ord chk
As Shown	SEEM		
Drawing size	Date	Date	Date
A3	Sep '17		

Status
 PLANNING