

MSA

MSA 70 Hatton Garden, London, EC1N 8JT.
www.msamited.com

Door Schedule
Date: 08.08.17
Site: 5 Great James Street
Project: 177
Revision: -

Door Number	Location	Original or of historic interest	Description of Existing Door	Existing Architrave	Existing Ironmongery	Photo Reference	Proposed Alterations	Fire resistance	Ironmongery	Drawing Reference
DR.01	Ground floor front door	Y	Solid 6 panel painted timber door	Existing historic. Painted.	Brass letter box Euro cylinder latch Unused mortise lock.	177-AD7-170818 Door Photo Reference 01	Existing door to be maintained and restored. Carefully remove existing paint finishes. Unused mortise locks to be removed, filled and sanded smooth. Door to be redecorated with paint to match the existing.	N/A	Door furniture to be maintained. New 3 hinge arrangement in style to match existing.	na
DR.02	Ground floor front door	Y	Solid 6 panel painted timber door	Existing historic. Painted.	Brass letter plate Chrome euro cylinder latch. Unused mortise lock. Chrome pull handle.	177-AD7-170818 Door Photo Reference 02	Existing door to be maintained, fire resistance improved and door restored. Carefully remove existing paint finishes. Influmescant smoke seal rebated into door edge. Door decorated in water based intumescent protection. Architraves maintained and redecorated.	FDS30	Full new ironmongery. 3 hinges right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-705
DR.03	Ground floor under stairs to basement	N	Painted timber and 4 glass panel door with metal reinforcement mesh behind.	Non-historic square profile.	Brass euro cylinder latch. Unused mortise lock. Brass pull handle.	177-AD7-170818 Door Photo Reference 03	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges, right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-706
DR.04	Ground floor to rear extension	N	Painted timber solid blank door.	Non-historic square profile.	Chrome euro cylinder latch. Two unused mortise with chrome rectangular escapements. Brass pull handle.	177-AD7-170818 Door Photo Reference 04	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges, right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-706
DR.05	Ground floor hall landing	N	Painted 4 panel timber door. Non-original tongue and groove matchboard partition wall above.	Non-historic painted decorative profile.	Painted euro cylinder latch and painted handle. Brass colour combination lock.	177-AD7-170818 Door Photo Reference 05	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob, Mortise turn and release WC lock.	177-706
DR.11	First floor landing	Y	Solid 6 panel painted timber door sealed shut.	Existing historic. Painted.	No visible ironmongery	177-AD7-170818 Door Photo Reference 06	Existing door to be maintained and fire resistance improved. Carefully remove existing paint finishes. Existing non-original timber panel covering internal door reveal to be removed. New internal self supporting timber stud wall to be introduced with plasterboard and skim made flush to panel wall. External face of door to be decorated in water based intumescent paint protection.	N/A	N/A	177-707
DR.12	First floor landing	Y	Solid 6 panel painted timber door	Existing historic. Painted.	Brass euro cylinder latch. Unused mortise lock. Brass door knob.	177-AD7-170818 Door Photo Reference 07	Existing door to be maintained, fire resistance improved and door restored. Carefully remove existing paint finishes. Influmescant smoke seal rebated into door edge. Door decorated in water based intumescent protection. Architraves maintained and redecorated.	FDS30	Full new ironmongery. 3 hinges right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-705
DR.21	Second floor landing	N	Light weight 6 panel painted timber door. Suspected asbestos panel to rear side. Single glazed 5 panel oval transom window above.	None	Chrome euro cylinder latch. Brass knob. Brass letter plate.	177-AD7-170818 Door Photo Reference 08	Door to be replaced with new 6 panel solid painted timber FDS30. To be completed in style to match DR.02. New painted architrave.	FDS30	Full new ironmongery. 3 hinges right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-708
DR.22	Second floor landing	N	Light weight 6 panel painted timber door. Suspected asbestos panel to rear side. Single glazed 5 panel oval transom window above.	None	Chrome euro cylinder latch. Brass knob. Brass letter plate.	177-AD7-170818 Door Photo Reference 09	Door to be replaced with new 6 panel solid painted timber FDS30. To be completed in style to match DR.02. New painted architrave.	FDS30	Full new ironmongery. 3 hinges right latch, mortice lock with internal thumb turn release. door knob, new letter plate.	177-705
DR.31	Third Floor Bedroom 02	N	Solid painted timber 2 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 10	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.32	Third Floor Bedroom 01	N	Solid painted timber 4 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 11	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.33	Third Floor Living room	N	Solid painted timber 4 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 12	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.34	Third Floor Bedroom 02	N	Solid painted timber 2 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 13	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.35	Third Floor Living room	N	Light weight painted timber 4 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 14	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.36	Third Floor Bathroom	N	Light weight painted timber 4 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 15	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706
DR.37	Third Floor WC	N	Light weight painted timber 4 panel door.	Non-historic square profile.	Steel door knob and hinges.	177-AD7-170818 Door Photo Reference 16	Replace door with new 4 panel solid painted timber door. To be fully FDS30. New architrave in style to match DR.02	FDS30	Full new ironmongery. 3 hinges door knob.	177-706