

INSPECTION CERTIFICATE FOR HYGIENE FACILITY



Report	J410800/HQ03	Date: 16 Oct 2017
Client Name	Medway Insulations Ltd	
Address	7 Viewpoint, Boxley Road, Penenden Heath, Maidstone, Kent, ME14 2DZ	
Site address for clearance	76669 / AB077 - 19-21 High Holborn, Grays Inn Chambers., WC1R 5ET	

THOROUGH VISUAL INSPECTION			
All waste debris, contaminated clothing, waste bags removed	Yes	Disturbance type:	BRUSHING
All surfaces are free from debris and settled dust	Yes	Area of shower end and dirty end:	<10 m ²
Manufacturers Serial No:	AMS 7	Duration of visual inspection:	5 mins

RESULTS			
Result:	PASSED	Date & time of inspection:	16 Oct 2017 14:03

COMMENTS: Satisfactory.

Clean End	Shower	Dirty End
	<div style="border: 1px solid black; padding: 2px;"> HQ004813 HQ004814 </div>	

Name: Lewis Harrison	Signature:
----------------------	------------

STOPWATCH NO:	MICROSCOPE USED:	TEST SLIDE NO: 000407 BLOCK 5 VISIBLE: Yes	STAGE MICROMETER NO:	GRATICULE DIAMETER:	FLOW METER NO.:	EXPOSED FILTER AREA:	BAROMETER NO.:	THERMOMETER NO.:	SITE TEMP:	SITE PRESSURE:	
004036	001924		000052	100 µm	003298	22.0 mm ²	000487	000487	16 °C	1022 mb	
SAMPLE NO.	TIME ON	TIME OFF	DURATION (mins)	PUMP NO.	INITIAL FLOW (L/Min)	FINAL FLOW (L/Min)	MEAN FLOW (L/Min)	VOLUME (L)	NO. OF FIBRES	NO. OF FIELDS	REPORTABLE CONC FIB/ML
HQ004813	13:12	13:32	20	004699	12.0	12.0	12.0	240	0.5	200	<0.01
HQ004814	13:12	13:32	20	002754	12.0	12.0	12.0	240	0.5	200	

Overall result: PASSED	Date & time of inspection: 16 Oct 2017 14:03
------------------------	--

THE HYGIENE FACILITY IS CLEARED FOR REUSE

COMMENTS: Satisfactory.

Name: Lewis Harrison	Signature:
----------------------	------------

CONTRACTOR'S REPRESENTATIVE ACKNOWLEDGEMENT

I have been advised by Lewis Harrison that an inspection certificate for the hygiene facility can be issued.

Name: Pat Ward	Signature:	Date: 16 Oct 2017	Time: 14:03
----------------	------------	-------------------	-------------