



No Entry into Goodge Place

Hoarding line 450mm back from kerb. Footpath closed

Chapter 8 used to form loading bay

From chapter 8 to kerb - 3.2m

1400mm clear footpath

Scaffold stopped inline with garage to allow pedestrian sight lines from zebra crossing

Hoarding around scaffold supports. 450mm back from kerb. maintaining clear pedestrian walkway

Hoarding line chamfered to allow good sightlines

- Key
- Scaffolding and Crash Deck (over pedestrian walkway)
 - Suspended Parking Bays (3 x standard)
 - Disabled Parking x 3 remain open at all times
 - Traffic gates controlled by traffic marshal / heris fencing
 - Lifting beam above gantry with lifting
 - Hoarding line
 - Pedestrian footpath closed
 - Pedestrian footpath under scaffold gantry to remain open