



Dear Sir or Madam,

Ref 110 Greencroft Gardens, London, NW6 3PH

We need to remove two trees at this property which are supporting a structurally unstable wall leaning in to our garden. I have put the information below:

Location – Rear Garden of 110 Greencroft Gardens

Trees to be removed

Cherry Tree (Pic 1)
Holm Oak (Pic 2)

Both trees are over 750mm in girth at 1.5mm and we plan to remove both trees

Kind regards,

Mark Lyness
Senior Property Manager

Akelius

Akelius Residential Ltd
5th Floor, Coin House
2 Gees Court
London
W1U 1JA

www.akelius.co.uk

Phone number: +44(0) 203 728 9227

Mobile: +44(0) 791 787 6022

mailto: mark.lyness@akelius.co.uk

England:
Registered Office:
Coin House 2, Gees Court London, W1U 1JA
Registered in England
Registration number: 7954505



