










EXISTING FRONT ELEVATION

	HIGHLY SIGNIFICANT
	HIGHLY SIGNIFICANT HARMED ELEMENT
	SIGNIFICANT
	SOME HISTORIC INTEREST
	NEUTRAL
	HARMFUL
	FRAGMENT

SUMMARY

- BRICKWORK ORIGINAL
- FLAT GAUGED BRICK ARCHES SIGNIFICANT
- 6 - OVER - 6 SASHES SIGNIFICANT (THEY ARE EITHER ORIGINAL OR GOOD REPLACEMENTS)
- FRONT DOOR AND FAN LIGHT SURVIVING ELEMENTS
- BRICKWORK FAIR
- SEE CONDITION SURVEY

SHOPFRONT NOT PART OF THE APPLICATION



T: +44 (0)20 8498 0211
 W: bridgetsheppard.com
 E: bridget.sheppard@btinternet.com

1A Bramley Close
 Woodford Green
 Essex. IG8 7PL

CLIENT
Venoru Ltd

PROJECT
49 Marchmont Street, WC1N 2AN

DRAWING
SURVEY OF SIGNIFICANCE FRONT ELEVATION

DRG. No 25	REVISION -
SCALE 1:50 @ A3 PAPER	DATE 14 JAN 2018