

Appendix 3 - Site photos

The photographs provided below were taken on 26.06.2017, prior to Deliveroo's occupation of the unit in August 2017. They are provided to show the original layout and state of the unit.

External



Image 1 – Entrance to the site from Finchley Road



Image 2 – Frontage of the site



Image 3 – Air condensers present at upper ground floor level



Image 4 – Rear elevation



Image 5 – Air condensers and bin storage along rear elevation



Image 6 – Image of unit from car park off Belsize Road

Internal



Image 7 – Service door and conveyor belt



Image 8 – Conveyor belt to upper ground floor level



Image 9 – Internal corridor



Image 10 – ductwork routed through the building



Image 11 – Room set out for office use



Image 12 – Room set out for office use



Image 13 – Unit in need of repair