

### NOTE

THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL OTHER RELEVANT DRAWINGS AND SPECIFICATIONS THIS DRAWING HAS BEEN PREPARED FOR IDENTIFICATION PURPOSES ONLY, VERIFICATION OF DRAWN INFORMATION TO BE CARRIED OUT BY CONTRACTOR PRIOR TO OTHER USE.

The window survey was an external inspection only - some assumptions regarding openings and window replacements have been made


Some windows are fitted with internal security bars

Original windows replaced - generally in

The window supplier must check all windows and opening arrangements


## Front elevation - 1









# Elevation - 4



Elevation - 3



Elevation - 5



**BELSIZE GROVE** 

Elevation - 2

SITE PLAN

scale 1:500

**GILLING COURT IDENTIFICATION PLAN** 

**Elevation - 6** 



- Milton House, 1 Milton Road, Peterborough PE2 8DZ Tel: 01733 344695
- 619 Holloway Road, London N19 5SS Tel: 020 7561 0189

Gilling Court, Belsize Grove 1735 WINDOW REPLACEMENTS -SV 01

**EXISTING ELEVATIONS** checked 1:100@A1 <sup>28.11.17</sup> RE


Elevation - 7



Elevation - 10 Elevation - 9



Elevation - 12 Elevation - 11



e Milton House, 1 Milton Road, Peterborough
PE2 8DZ Tel: 01733 344695
e 619 Holloway Road, London N19 5SS Tel: 020
7561 0189
project
Gilling Court, Belsize Grove

drawing
WINDOW REPLACEMENTS - SV 02
EXISTING ELEVATIONS
scale date drawn checked
1:100@A1 28.11.17 RE

NOTE

security bars

THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL OTHER RELEVANT DRAWINGS AND SPECIFICATIONS

THIS DRAWING HAS BEEN PREPARED FOR IDENTIFICATION PURPOSES ONLY, VERIFICATION OF DRAWN INFORMATION TO BE CARRIED OUT BY CONTRACTOR PRIOR TO OTHER USE.

The window survey was an external inspection only - some assumptions

Some windows are fitted with internal

Original windows replaced - generally in


The window supplier must check all windows

regarding openings and window replacements have been made

and opening arrangements




## Front elevation - 1




Roof level not surveyed



Roof level not surveyed








Roof level not surveyed

**Elevation - 6** 

**Elevation - 5** 



## Elevation - 2



NOTE

THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL OTHER RELEVANT DRAWINGS AND SPECIFICATIONS THIS DRAWING HAS BEEN PREPARED FOR IDENTIFICATION PURPOSES ONLY, VERIFICATION OF DRAWN INFORMATION TO

BE CARRIED OUT BY CONTRACTOR PRIOR TO OTHER USE.

The window survey was an external inspection only - some assumptions regarding openings and window replacements have been made

Some windows are fitted with internal security bars

All windows to be replaced with the Alitherm Heritage aluminium system and are to closely match the original window design.

The window supplier must check all windows and opening arrangements

### **Alitherm Heritage Windows**

The replacement windows are to be Alitherm Heritage design with fixed light and open-out windows, internally and externally

All opening vents are hung on concealed stainless steel variable angle friction stays and fitted with cockspur/espagnolette locking mechanisms.

Internal beads and gaskets will accommodate 24, 28, 32 &

Thermal breaks are formed with polyamide strips PA 6.6 25 reinforced with glass fibre, fitted between aluminium extrusions. All profiles are extruded from aluminium alloy 6060/6063 T5/T6 and comply with the recommendations of BS EN 12020-2; 2001/BS 755-9: 2001.

Profiles are to be Electrostatic powder coat finished in white

Smart Systems Ltd. Arnolds Way, Yatton, North Somerset BS49 4QN.

Fax: 01934 835169. Email: sales@smartsystems.co.uk

www.smartsystems.co.uk

All windows, in conjunction with a suitable glazing specification, to achieve an average project U-value to meet the current requirements of the approved Building Regulation Document

1735

checked

GA 01


RE


L1/L2 for England and Wales.


Sûrveyors LLP Milton House, 1 Milton Road, Peterborough PE2 8DZ Tel: 01733 344695 619 Holloway Road, London N19 5SS Tel: 020 7561 0189 Gilling Court, Belsize Grove

Roof level not surveyed

Elevation - 7









Elevation - 10 Elevation - 9








Elevation - 11

## **Elevation - 8**



### NOTE

THIS DRAWING IS TO BE READ IN CONJUNCTION WITH ALL OTHER RELEVANT DRAWINGS AND SPECIFICATIONS THIS DRAWING HAS BEEN PREPARED FOR IDENTIFICATION PURPOSES ONLY, VERIFICATION OF DRAWN INFORMATION TO BE CARRIED OUT BY CONTRACTOR PRIOR TO OTHER USE.

The window survey was an external inspection only - some assumptions regarding openings and window replacements have been made

Some windows are fitted with internal security bars

Original windows replaced - generally in

The window supplier must check all windows and opening arrangements

### **Alitherm Heritage Windows**

The replacement windows are to be Alitherm Heritage design with fixed light and open-out windows, internally and externally

All opening vents are hung on concealed stainless steel variable angle friction stays and fitted with cockspur/espagnolette locking mechanisms.

Internal beads and gaskets will accommodate 24, 28, 32 &

Thermal breaks are formed with polyamide strips PA 6.6 25 reinforced with glass fibre, fitted between aluminium extrusions. All profiles are extruded from aluminium alloy 6060/6063 T5/T6 and comply with the recommendations of BS EN 12020-2; 2001/BS 755-9: 2001.

Profiles are to be Electrostatic powder coat finished in white

Smart Systems Ltd. Arnolds Way, Yatton, North Somerset BS49 4QN.

Fax: 01934 835169. 01934 876100. Email: sales@smartsystems.co.uk

www.smartsystems.co.uk

All windows, in conjunction with a suitable glazing specification, to achieve an average project U-value to meet the current requirements of the approved Building Regulation Document

L1/L2 for England and Wales.

Milton House, 1 Milton Road, Peterborough PE2 8DZ Tel: 01733 344695 619 Holloway Road, London N19 5SS Tel: 020 7561 0189 no Gilling Court, Belsize Grove 1735

GA 02

RE

checked