

Applicant
 Jay Soneji
 Brahm Property Limited
 1 Motcomb Street
 London
 SW1X 8JU

e: jay@brahmpropertygroup.co.uk
 t: +44 (0)20 7235 8861

Agent
 George Curtis BSc (Hons) MRICS
 JLL
 30 Warwick Street
 London
 W1B 5NH

e: george.curtis@eu.jll.com
 t: +44 (0)20 7399 5689

Tree Locations

T1:	T2 & T3:
Linfield House	10 Langland Gardens
London	London
NW3 6PR	NW3 6PR

Affected Trees


T1:	Large tree located within the boundary of Linfield House. Species unknown.
T2:	Small tree located within the boundary of 10 Langland Gardens. Species unknown.
T3:	Small tree located within the boundary of 10 Langland Gardens. Species unknown.

Proposed Works

The boundary wall between 10 Langland Gardens and Linfield House is in poor repair and is in danger of collapse. The wall has been inspected by a structural engineer who has specified a replacement using a hollow block system with reinforcement. These works will effect three trees located near to the boundary between 10 Langland Gardens and Linfield House.

The works have potential to impact the roots of tree T1, we will look to remove or reduce any risk of damage to this tree during the works. Trees T2 and T3 are damaging the existing wall and will need to be removed as part of the works.

Plan





T1 (Large tree to rear)



T2 & T3

Declaration

12 March 2018

George Curtis BSc (Hons) MRICS

JLL

30 Warwick Street

London

W1B 5NH

e: george.curtis@eu.jll.com

t: +44 (0)20 7399 5689

m: +44 (0)7713 780 903