

		Geotechnical Testing Analysis Report		 environmental claims mgmt subsidence drainage	
Unit 3 & 4, Heol Aur, Dafen Ind Estate, Dafen Llanelli, Carmarthenshire, SA14 8QN				Auger House, Cross Lane, Wallasey, Wirral, CH45 8RH	
<u>Summary Of Claim Details</u>					
Policy Holder					
Risk Address		25 Frogna London NW3 6AR			
SI Date		19/12/2018 + 17/01/2018			
Issue Date		20/12/2018 + 18/01/2018			
Report Date		03/01/2018 +24/01/2018			
Auger Reference		75715.1.2.RSS + 75715.1.6.RSS			
Insurance Company		Legal & General Insurance			
LA Claim Reference					
LA Co. Reference		Cunningham, Lindsey			
This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.					
	Checked	24/01/2018	Wayne Honey		
	Approved	24/01/2018	Ben Sharp		
					

[illegible]

