

**Level Monitoring**

**Our Ref: 471957**

**Date of Issue: 09/03/2018**

**Provider Details**

**CET Property Services - 0116 2605309**

**Monitoring Details**

<b>Instruction Date:</b>	<b>06/11/2017</b>		
<b>Number of visits</b>	<b>4</b>	<b>Visit Frequency (Wks)</b>	<b>8</b>

**Visit Dates (future dates are estimated)**

<b>Setup</b>	<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>
<b>14/11/17</b>	<b>09/01/18</b>	<b>06/03/18</b>	<b>01/05/18</b>	<b>26/06/18</b>	<b>NA</b>	<b>NA</b>

**Client Details**

<b>Insurance Co.:</b>	<b>Prestige Underwriting Services Ltd</b>
<b>Client Ref:</b>	<b>6562721</b>
<b>Client Name:</b>	<b>Cunningham Lindsey</b>
<b>Technical Mgr:</b>	
<b>Customer support</b>	<b>Paula Haythornthwaite</b>
<b>Tel:</b>	<b>01622 608851</b>
<b>Email:</b>	<a href="mailto:paula.Haythornthwaite@cl-uk.com">paula.Haythornthwaite@cl-uk.com</a>


**Risk Address**

<b>Occupier:</b>	<b>Miss Hartono &amp; Mr Howson</b>
<b>Address:</b>	<b>88 Albert Street</b>
<b>Address:</b>	
<b>Town:</b>	<b>London</b>
<b>County:</b>	
<b>Post Code:</b>	<b>NW1 7NR</b>
<b>Contact Name</b>	<b>Mr Griffiths</b>

**Level Monitoring - Site Sketch**

Our Ref: 471957


Date of Issue: 09/03/2018







Level Monitoring - Movement relative to datum against Date



4.80

7.84

2.84

3.00

1.96

4.66

6.60

3.92

4.27



Our ref	Client ref	Client Name	Issue Date
471957	6562721	Cunningham Lindsey	09/03/2018

#### Stud locations

1	INT- Flat A 2/F front right room to left of window high (Steps)
2	INT Flat A 1/F living room front elevation near left corner (Ladder)
3	INT- Flat A 1/F Living room left elevation above door (ladder)
4	EXT- front elevation below GF window sill
5	EXT- Front elevation Basement floor below window
6	

Additional instructions / notes

### Crack Monitoring - Readings

Studs nos.	Align-ment	Visit Date	14/11/17	Visit Date	12/01/18	Visit Date	09/03/18	Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	61.98	4.50	62.06	4.80	61.90							
1	D	63.88	7.55	63.90	7.84	63.56	7.88						
1	Check	84.43		84.47		84.47							
2	H	57.24	2.82	57.18	2.61	57.09	2.69						
2	D	63.44		63.30	2.84	63.26							
2	Check	40.16		40.19		40.15							
3	H	61.12	2.88	61.23	3.00	61.20							
3	D	55.88		55.94	1.96	55.86							
3	Check	85.34		85.40		85.45							
4	H	70.51	4.39	70.51	4.66	70.37							
4	D	93.44		93.52	6.60	93.45							
4	Check	52.98		52.94		52.94							
5	H	60.72	3.81	60.81	3.92	60.73							
5	D	78.41		78.61	4.27	78.66							
5	Check	54.38		54.42		54.41							
6	H												
6	D												
6	Check												
Calliper nos :		9839		9839		4190							
Technician :		AJZ		AJZ		AJZ							

Our ref	Client ref	Client Name	Issue Date
471957	6562721	Cunningham Lindsey	09/03/2018

### Crack Monitoring - Movement Against Time

