| Earth Environmental E Gestechnical E Gestechnical E Gestechnical E Gestechnical E Gestechnical E Gestechnical E Gestechnical E Stockport E Gestechnical E Gestechnical E Stockport E Gestechnical E Gestechn | | | | | Borehole No. | | | |
|--|----------------------------------|--------------------------|----------------|----------------------|--------------|-------------|--------------------------------|-------------------|
| | | | | | BH01 | | | |
| | SK5 6D | A | | D 1 (N) | | - | | Sheet 1 of 1 |
| Project Name | e: 246 Belsiz | ze Road | l | Project No. A1451 | | Co-ords: | - | Hole Type WS |
| | | | | | A1451 | | | Scale |
| Location: | London | London | | | | | | 1:10 |
| Client: | Grosveno | Grosvenor Square Estates | | | | | 20/02/2018 - | Logged By LG |
| Well Water Strikes | | <u>т т</u> | n Situ Testing | Depth (m) | Level (m) | Legend | Stratum Description | |
| | ^s Depth (m) | Туре | Results | 0.03 | () | | Concrete paving slab (MADE GRO | JND) |
| | | | | 0.00 | | | Dark grey concrete (MADE GROUN | ID). |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | 0.28 | | | Stiff reddish brown CLAY. | |
| | | | | | | F | PID 0.30m 0.0ppm | |
| | | | | | | F | | |
| | | | | | | E | | |
| | | | | | | E | | |
| | | | | | | E- <u>-</u> | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | D/D 0.75m 0.0mm | |
| | | | | 0.80 | | | PID 0.75m 0.0ppm | |
| | | | | 0.85 | | | Weak light brown MUDSTONE. | |
| | | | | | | | End of borehole at 0.65 m | |
| | | | | | | | | |
| | | | | | | | | 1 - |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | 2 - |
| Remarks | | nrior t- | execution | | | | | |
| Monitoring in | nned with CAT stallation: 0.4 | m plain, | 0.4m slotted. | | | | | Earth Environment |

| Earth Environmental & Gestechnical B Gestechnical | | | | | Borehole No. | | | | | |
|---|------------------|--------------------------------|----------------------|----------------------------------|--------------|--------------|-----------------|--|-----------------------------------|-------|
| | | | | | BH02 | | | | | |
| SK5 6DA | | | | | 1 | | Sheet 1 of 1 | | | |
| | | | Project No. A1451 | | Co-ords: - | | Hole Type WS | | | |
| | | London | | | | | | | Scale | |
| Locati | on: | London | | | | | Level: | | 1:10 | |
| Client: Grosvenor Square Estates | | | | | Dates: | 20/02/2018 - | Logged By | | | |
| Well | Water Strikes | | 1 T | n Situ Testing Results | Depth (m) | Level (m) | Legend | Stratum Description | | |
| | Strikes | Depth (m) | Туре | Results | | | Legend | Concrete paving slab (MADE GROUN Dark grey concrete (MADE GROUN Stiff reddish brown CLAY. PID 0.50m 0.0ppm End of borehole at 1.00 m | JND). ID). | |
| | | | | | | | | | 2 | |
| Rema Locati Monite | on scan | ned with CAT tallation: 0.5 | prior to | o excavation. , 0.5m slotted. | | 1 | | | Earth Environme & Geotechnical | antal |