Application No:	Consultees Name:	Consultees Addr:	Received:	Comment:	Printed on: 10/04/2018 09:10:04 Response:
2017/4622/P	Patricia Barson	60 Grafton Road NW5 3DY NW5 3DY	26/03/2018 18:11:09	AMEND	As my comments are rather long and complicated I have sent emails to planning@camden.gov.uk and Rob.Tulloch@camden.gov.uk
2017/4622/P	Richard Haynes	60b Grafton Rd London NW53DY	03/04/2018 16:15:16	COMMNT	As a neighbour I am concerned about the maintenance of building quality if permission is given.
					When given permission to remove fireplaces to the property, the poor standard of building work resulted in large visible cracks to the front exterior wall of the house. These damages have been left un-repaired for over four years.
					Anthony Fieldhouse & Co. Chartered Surveyors described the state of 58 Grafton Rd in a letter dated June 24, 2014 to Patricia Barson flat A 60 Grafton Rd:
					"Diagonal cracks across the front of the building at ground floor level have left the property in a potentially dangerous position"
					As a neighbour I am concerned that again poor building work will threaten the structure of my house.
					Yours sincerely, Richard Haynes