

CRACK MONITORING

for Subsidence Management Services

8 Brookfield Park, London, NW5 1ER

Client:	Subsidence Management Services
Client Contact:	Cyril Nazareth
Claim Number:	102024304
Client Reference:	IFS-LBG-SUB-17-0073223
Policy Holder:	Mrs Inger Freeman
Report Date:	25 April 2018
Our Ref:	M10694

Crack Monitoring Readings


The following table shows the reading levels of the Crack Monitoring Stations.

Date	A=B (H)	B=C (D)	A=C (V)(C)	Crack Width
C1 - INT - Kitchen, above side window				
12 February 2018	81.97	106.37	71.58	3.40 - 2.50
20 April 2018	81.81	106.13	71.60	
Date	A=B (H)	B=C (D)	A=C (V)	Crack Width
C2 - INT - Kitchen, below side window				
12 February 2018	71.57			2.00
20 April 2018	71.22			1.70

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.

C1 - INT - Kitchen, above side window



C2 - INT - Kitchen, below side window



Site Visit Notes