

Proposed Planting

Types of plants proposed across the South Garden



East Wall



Temporary Removal of 4m Section

We intend to seek approval for the temporary removal of a 4m section of the back brick garden wall to Albany Street, in order to support the proposals.

We have chosen to seek approval in this location in order to create a practical and suitable access for the ground source heat pump drilling rig and eventual main building works entrance. On consultation with the Church Committee, this was deemed unanimously preferrable than to providing main access from the listed front precint through the fragile stone arches.

On further investigation, the brick wall to the back of the site in the denoted segment (see drawings to right) is cracking at two points, largely due to a leaning cherry tree with exposed roots. As the brick wall falls within the curtilage of the Church's Grade II* listing and possesses an attractive patina, we would propose to carefully deconstruct and safely store the bricks during the construction period and reconstruct on the completion of building works. We understand this process has previously been agreed at prior developments to residential homes in St. Katharine's Precinct (see p.8), so as to avoid disruption to the Listed Precinct.

We would seek approval for the removal of Ino. unhealthy cherry tree highlighted and a small tree adjacent and propose their like-for-like replacement following the building works.

During the building works, high-quality hoarding will be erected to secure this temporary building entrance to the site.



KEY

Existing walls

Demolished extent

Plan
150



Precedent for temporary brick wall removal within St. Katharine's Precinct, during works on a private residence



Albany Street elevation



Existing cracks to wall



Church yard elevation

- Current back gate to church garden

Cherry tree leaning on wall we would propose to replace the cherry tree following the reconstruction of the brick wall

------ Exposed root to cherry tree

9 | APPENDIX

Schedule of Works

Refurbishment

North Wing

GIA Refurbishment Total= 199m²

The Vicarage

GIA Total = **506m**²

GIA New Dormer Total = 22m² GIA Refurbishment Total = 285m²

GIA Total = **307m**²

Landscape

78

Sunken Terraces - South Garden

West Terrace **27m²** (55m² inc. steps)
East Terrace **12m²** (25m² inc. steps)

North Wing


	Level	Room No.	Name	Area	Description of Works
	GF	1	Entrance Hall	14 m²	a. Relocation of stair to basement - demolition of 1600x 2550mm area in concrete floor slab to create new stair void b. Refurbishment to windows and sashes, general making good of finishes.
		2	Hall Café	24 m²	a. Relocation of western enclosing wall to Hall Café. b. General refurbishment and improvements of finishes, windows sash repair.
		3	Hall	50 m²	a. General refurbishment, making good and improvements to floors and finishes, window sash repair.
		4	Serving Kitchen	6 m²	a. Relocation of serving kitchen to flank Nave wall b.Improvements to finishes and provisions.
		5	Accessible WC	3 m ²	a. Installation of an accessible WC at ground level adjacent to the Church Hall, where existing serving kitchen is located.
	В	6	Corridor	15 m²	a. High-quality floor material installed, denoting public spaces in basement. b. Extending 1no. existing window to terrace to create a fire escape door.
		7	Shop	8 m²	a. Relocation of shop - to create a purpose-built space, providing more storage with high-quality joinery.
ng		8	Women's WC	9 m²	a. Demolition of wall partitions in basement to move WCs to back wall.
North Wing		9	Men's WC	7 m²	a. Demolition of wall partitions in basement to move WCs to back wall.
		10	Hot Kitchen	14 m²	a. Demolition of wall partitions in basement to consolidate, improve and expand kitchen facilities. b. Installation of 2no. kitchen external vents above windows (250 x 600mm) to façade. Closing up and making good of 1no. existing external vent. The current ventilation is insufficient for the capacity of the church's kitchen.
		11	Prep Kitchen	13 m²	a. Introduction of a prep kitchen area with a connection to the store rooms. b. Extending existing vent opening below external staircase to create fire escape door to terrace from the kitchen.
		12	Existing Store	9 m²	a. Excavation below the church hall to extend basement space and essential food storage provision. b. Create an external entrance and stair for deliveries and kitchen access from the back garden. Demolition of 1no. door opening to eastern basement wall.
		13	Store Room	24 m²	a. Charming brick vaulted store room retained as is.
		14	Cupboard	1 m²	a. Installation of boiler in cupboard to heat the North Wing. b. Install boiler flue termination in existing vent to the north façade.
		15	WC Store	1 m²	a. Cupboard space to store cleaning supplies.
		16	WM Cupboard	1 m²	a. Cupboard space to store linen and washing machine facilities.

The Vicarage

	Level	Room No.	Name	Area	Description of Works
Vicarage		17	Vault Store	7 m²	a. Charming brick vaulted store room retained as is.
		18	West Meeting Room	24 m²	a. Removal of radiators below windows and installation of new glazed crittal doors to terrace. b. Refurbishment and general making good of finishes.
	В	19	Mini-flat	12 m²	a. Removal of existing kitchen and introduction of a flexible meeting room / compact self-contained flat for visitors. b. Dropping of sill to 1no. window opening to create glazed crittal door to terrace.
		20	Stair	3 m²	a. Existing stair retained.
		21	Kitchenette	1 m²	a. Installation of a compact kitchenette to furnish the mini-flat and meeting rooms.
		22	Shower Room	4 m²	a. Installation of a bathroom with shower below the stairs to furnish the mini-flat.
		23	Entry Hall	12 m²	a. General refurbishment, making good and improvements to floors and finishes. b. Installation of storage cupboards.
		24	WC1	2 m ²	a. Installation of upgraded WC facilities.
		25	WC 2	3 m²	a. Installation of upgraded WC facilities.
		26	Storage	2 m ²	a. Existing store cupboard retained as is.
		27	East Meeting Room	41 m²	a. Dropping of sill to 1no. window opening to create fixed glazed opening to terrace. b. General refurbishment, making good and improvements to floors and finishes.
		28	Walkway	8 m²	a. Demolition to existing wall partition below external stairs b. Creation of Ino. arched opening to eastern wall of brick enclosure to create link between terraces. c. General refurbishment, making good and improvements to floors and finishes.
		29	Store 1	1 m²	a. Existing external store cupboard retained as is.
		30	Store 2	1 m²	a. Existing external store cupboard retained as is.
	GF	31	Living Room	25 m²	a. Demolition and reinstatement of 1no. symmetrical door opening to the Living Room from stairwell. b. Refurbishment to windows and sashes, general making good of finishes. c. High-quality timber joinery cupboards installed to north wall.

	Level	Room No.	Name	Area	Description of Works
Vicarage	GF	32	Stairwell	8 m ²	a. Existing 19thC curved stair retained. b. Demolition in dropping of 1no. existing window sill in eastern enclosing wall of stairwell to create connection to new dormer bedroom (920 x 2380mm opening below window). Opening detailed to sit above existing stair stringer.
		33	Study	12 m ²	a. General making good and improvements to windows, floors and finishes.
		34	Entrance Hall	10 m ²	a. Demolition of existing non-structural wall partitions, later additions in 1950s refurbishment. b. General making good and improvements to floors and finishes.
		35	WC	2 m ²	a. Installation of new cloakroom WC.
		36	Kitchen	16 m ²	a. Installation of new kitchen and high-quality joinery storage cupboards. b. General making good and improvements to windows, floors and finishes.
		37	Living / Dining	34 m ²	a. Removal of suspended ceiling to reveal ornamental wooden roof trusses, rose window to east wall and reinstate doubleheight space.
	FF	38	Master Bedroom 1	22 m ²	a. General making good and improvements to windows, floors and finishes.
		39	Ensuite Bathroom	5 m ²	a. Removal of existing bathroom and dividing of space to install a new ensuite bathroom to Master bedroom.
		40	Bathroom	5 m ²	a. Removal of existing bathroom and dividing of space to install a new family bathroom.
		41	Washing Machine	1 m ²	a. Installation of cupboard to house washing machine and hot water cylinder.
		42	Bedroom Corridor	11 m ²	a. General making good and removal of later flooring, replacing with high-quality floors and finishes.
		43	Bedroom 2	13 m ²	a. General making good and improvements to windows, floors and finishes.
		44	Dormer Entrance	2 m ²	Skylight installed in dormer roof to bring light to existing window on eastern enclosing wall to stairwell
		45	Bedroom 3	19 m²	a. Partial dormer created and concealed in northern face of Vicarage roof to house an important third bedroom. The dormer sits inbetween the old gable wall and ornamental roof trusses, which are exposed in the room. b. 2no. heritage rooflights are installed to south face of pitched Vicarage roof to bring light to bedroom. c. Built-in timber joinery installed to create eaves storage and desk. d. Window installed on eastern face of enclosing dormer wall to create horizontal view out from desk area.
		46	Boiler Cupboard	1 m ²	a. Tall cupboard created off of dormer entrance to house boiler and storage.

79



Basements 1:100

