



1.Structural Engineer's sketches of Sauna building slab





2. Analysis of impact of Sauna building on surrounding tree Root Protection Areas (shows that all below threshold of negative mpact)