

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Street View (looking North/East) - 76 Delancey Street within box.

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Front Elevation 76 Delancey St



Rear Elevation 76 Delancey St

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Rear of 74 Delancey St



Rear of 78 Delancey St

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Ground Floor Interior – Entrance to 76A Delancey St



Ground Entrance Lobby – Existing Cornices

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Entrance Door to 76B Delancey St at 1st Floor Level



Stair rising to entrance of 76B Delancey St

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlegmail.com



Stair rising from 1st Floor Landing



Entrance Door to 76B at 1st Floor Level

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



1st Floor Landing looking through ex'g opening to Front Room



Current Kitchen & Lobby arrangement. Lobby to be removed.

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Current Kitchen Arrangement to Front Room - 1st Floor



1st Floor Front Room

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



1st Floor Front Room Interior (06/06/2008)



1st Floor Front Room Interior (06/06/2008)

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



1st Floor Front Room – Shutters to Windows Retained



2nd Floor Front Room – Existing Timber Sliding Sash Windows

Site Photographic Report


76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Stair between 1st & 2nd Floor



2nd Floor Landing looking towards bathroom

Site Photographic Report


76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



2nd Floor Landing looking towards Stair




Stair rising from 2nd Floor to Roof Terrace

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Access to Roof Terrace



2nd Floor Stair rising to Roof Terrace

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Roof Terrace – Front of Building



Stair enclosure and Roof Terrace Area



Site Photographic Report


76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Roofscape View towards 78, 80 & 90 Delancey St



Roofscape View towards 74, 72 & 70 Delancey St

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@gmail.com



Rear Part of Roof Terrace looking towards 74 Delancey St

Roofscape View towards 74, 72 & 70 Delancey Street

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Rear Elevation and Garden Patio of 76 Delancey St




Rear Garden of 76 Delancey St

Site Photographic Report

76 Delancey Street
London NW1 7SA

MAAPS

Mance Architectural & Planning Services
maapsuk@googlemail.com



Front Elevation of 76 Delancey St (from Roof Terrace)



Front Elevation and balcony of 76 Delancey St (from 2nd Floor)