




Opening GF Closet Wing internal wall



Further investigation of rear external closet wing from GF internal position



Non original brickwork evident at top of closet wing

