

















Photo 9 – 20.02.2018 – Ground,  $1^{st}$  and  $2^{nd}$  Floor Windows to East Section of Front Elevation, North to South, from East End of Gower Place



Photo 10 – 20.02.2018 – Rainwater Goods to East Section of Front Elevation, north to South, From East End of Gower Place

















































