
















| Photograph number | Photograph Description | Photograph |
|-------------------|------------------------|---|
| 1. | Front Elevation |  A photograph showing the front elevation of a three-story brick house. The house features a prominent bay window on the ground floor, a central front door with a set of concrete steps, and two windows on the second floor. The brickwork is a mix of red and brown tones. |
| 2. | Rear Elevation |  A photograph showing the rear elevation of the brick house. The view is partially obscured by dense green foliage, including large plants and trees. A window is visible on the second floor. |
| 3. | Side Elevation |  A photograph showing the side elevation of the brick house. The house has a gabled roof and a single window on the ground floor. The brickwork is visible, and there are utility poles and wires in the foreground. |

| Photograph number | Photograph Description | Photograph |
|-------------------|--|---|
| 4. | Bay Window |  A photograph showing a three-story brick building with a prominent bay window on the second floor. The window has white trim and a decorative top. A black downspout is visible to the left of the window. A brick pillar with a sign is in the foreground. |
| 5. | Communal Entrance To Flats 14 B & 14 C |  A photograph of a black door with a white arched transom above it, set in a brick wall. The door has a silver handle and a small window with a decorative pattern. The number '14' is visible on the door. A white chair is partially visible to the right. |
| 6. | Entrance To 14 A |  A photograph of a white door set in a brick wall. The door is slightly ajar. A sign above the door reads '14 A'. A concrete step leads up to the door. A white handrail is visible on the right side of the door. |

| Photograph number | Photograph Description | Photograph |
|-------------------|------------------------|--|
| 7. | Rear Entrance To 14 A |  A photograph showing the rear entrance to a property. The entrance features a white door set within a brick wall. To the left of the door is a decorative wall-mounted object, possibly a birdhouse or a similar ornament. To the right is a window with white frames. The entrance is reached via a small concrete path. |
| 8. | Window Close Up |  A close-up photograph of a window. The window has white frames and is set in a brick wall. A flower box filled with red and orange flowers is mounted on the windowsill. |
| 9. | Window Close Up |  A close-up photograph of a window. The window has white frames and is set in a dark brick wall. The window is slightly open, and the view outside is visible through the panes. |

| Photograph number | Photograph Description | Photograph |
|-------------------|------------------------|--|
| 10. | Window Close Up |  |
| 11. | Window Close Up |  |
| 12. | Window Close Up |  |

| Photograph number | Photograph Description | Photograph |
|-------------------|-------------------------|---|
| 13. | Window Close Up |  A close-up photograph of a window set in a brick wall. The window is covered with white metal bars. The top of the window frame is arched and made of red brick. The surrounding wall is made of yellowish-brown bricks. |
| 14. | Window Close Up |  A close-up photograph of a window set in a brick wall. The window has white curtains and is covered with a white metal grate that has a diamond pattern. The top of the window frame is arched and made of red brick. The surrounding wall is made of yellowish-brown bricks. |
| 15. | Below Street Level Area |  A photograph of a narrow, dark area below street level. It shows concrete steps leading up to a doorway. The area is bordered by a brick wall on the left and a white wall on the right. There are some plants in pots on the left side. |