



|  |  |  |             |   |
|--|--|--|-------------|---|
| <b>Simon Pryce Arboriculture</b><br><br>CP House,<br>Otterspool Way,<br>Watford,<br>WD25 8HP<br>tel 01923 467600<br><a href="mailto:info@simonpryce.co.uk">info@simonpryce.co.uk</a><br><a href="http://www.simonpryce.co.uk">www.simonpryce.co.uk</a> | <b>Client:</b><br>Ms G Scardaccione                  | <b>Ref:</b><br>18/037                                      | <b>Rev:</b> | <b>Notes:</b><br><br><br><br><br>Crown Copyright 2018<br>Reproduction in whole or in part is prohibited<br>without the prior permission of Ordnance Survey. |
|  | <b>Site:</b><br>36 Elsworth Road, London,<br>NW3 3DL | <b>Scale:</b><br>1:100 at A4                               |             |   |
|  | <b>Title:</b><br>Tree and damage to wall             | <b>Original drawing:</b><br>Simon Pryce on<br>OS base plan |             |   |
|  | <b>Date:</b><br>13 July 2018                         |  |             |   |