

LOCATION

1 THE MOUNT

PROPOSALS

Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic

Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic

Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic

WINDOW SCHEDULE

WINDOW

| WLG01 | Family Room/Dining | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
|-------|--------------------|---|
| WLG02 | Kitchen | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| WLG03 | Utility Room | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| WLG04 | Rear Porch | Existing window to be removed |
| WLG05 | Stairwell | Existing window with coloured marginal panes to be retained |
| WG01 | Reception | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| WG02 | Study | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| WG03 | Servery | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| WG04 | Stairwell | Existing window with coloured marginal panes to be retained |
| W101 | Master Bedroom | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| W102 | Master Bedroom | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| W103 | Dressing Room | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| W104 | En-suite | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |
| W105 | En-suite | Upgrading of existing sashes using high performance 'Histoglass Mono' single glazing. Installation of more authentic window furniture |

General Notes:

W201

W202

W203

- Where existing, security grilles to windows and doors at basement and ground floor level to be removed.

window furniture

window furniture

window furniture

- Where existing, perforated lining to window jambs in basement to be removed.
- Where existing, insect screens to be removed.

Bedroom 2

Bedroom 2

Family Bathroom