Client: Kenny Project: 8 Cliff F Survey Date: 24/09/2 Surveyor: Richard						385	C	12 Tree S	Survey		Connick Tree Consultancy New Pond Farm Woodhatch Road Reigate Surrey RH2 7QH Phone: 01737 779 191			
Tree and Tag No		Hght	Stems			Crown			RP	Phys	Structural		Preliminary Recommendations	
Species	ies		No	Ø (mm)	Spread (m)	Clear (m)		Age	A (m²) R (m)	Condition	Condition		Survey Comment	
T1 Not tagge	d												Estimated Me	easurement
Common Ash		23	1	500	Ν	5	8	М	A: 113.1	Good	C: Good	No act	ion :: Unspecified	B.2
Fraxinus excelsior					E S W	5 5 5	8 8 8		R: 6		S: Ivy B: Good	Tree ir wall, iv	n neighbouring property growing within 2m of building y obscuring full inspection of trunk and crown. No close tion could be made due to location of tree in third party	>40 yrs
T2 Not tagge	d												Estimated Me	asurement
Common Pear <i>Pyrus communis</i>		9	1	250	N E	2 2	4 4		A: 28.3 R: 3	Good	C: Good S: Fair		ion :: Unspecified	B.2 >40 yrs
					S W	2 2	4 4				B: Fair		n neighbouring property. No close inspection could be due to location of tree in third party property	
r3 Not tagge	d												Estimated Me	asurement
Bay <i>Laurus nobilis</i>		10	1	300	N E	3 3	2 2	Μ	A: 40.7 R: 3.59	Good	C: Good S: Good	No act	ion :: Unspecified	B.2
					S	3	2				B: Fair		n neighbouring property on fence line . No close	>40 yrs
					W	3	2					proper	tion could be made due to location of tree in third party ty	
r4 Not tagge	d												Estimated Me	asurement
Common Ash		6	1	190	Ν	4	1	Y	A: 16.3	Fair	C: Fair	No act	ion :: Unspecified	C.2
Fraxinus excelsior					E	2	4		R: 2.27		S: Fair	Troo in	n neighbouring property within 4m of boundary wall. No	>40 yrs
					S W	1 4	4 3				B: Fair	close i	nspection could be made due to location of tree in third property	
Age Classifications:	N Y	Newly plante Young	ed	EM Earl M Mate	-		С	ondit	ion: C S	Crown Stem		Stems:	Ø Diameter (Eq) Equivalent stem diameter using BS5837:2012 de	finition
		Semi-matur	е	OM Ove					B	Basal area	1	ERC:	Estimated Remaining Contributio	
Page 1									TreeM	linder			ů – – – – – – – – – – – – – – – – – – –	mber 2018

Connick Tree Care

Tree and Tag No			S	tems	Cr			RP		.	Preliminary Recommendations	Cat	
Species		Hght (m)	No	Ø (mm)	Spread (m)	Cle (m		Age	A (m²) R (m)	Phys Condition	Structural Condition	Survey Comment	
5 Not	tagged											Estimated Meas	suremer
Common Ash		24	1	600	Ν	7	9 M	M A	A: 162.9	Good	C: Good	No action :: Unspecified	B.2
Fraxinus excelsior					Е	7	9	F	R: 7.2		S: Good		>40 yı
					S W	7 7	8 9				B: Fair	Tree in neighbouring property within 3m of building wall . No close inspection could be made due to location of tree in third party property, tree crown has been reduced in past.	,
6 Not	tagged											Estimated Meas	sureme
1agnolia		5	1	120	Ν	2	1 Y		A: 6.5	Good	C: Good S: Fair	No action :: Unspecified	B.2
Magnolia Spp.					E	2	1	F	R: 1.43				20 to 4
					S W	2 1 2 1				B: Fair	Tree in neighbouring property within 1m of boundary wall, no close inspection could be made due to location of tree in third party property	yrs	
Age Classifications:				EM Early			Co	nditio				Stems: Ø Diameter	_
	Y	Young		M Matu	re				S	Stem		(Eq) Equivalent stem diameter using BS5837:2012 defin	nition
		Semi-matur		OM Over	• • ·				В	Basal area		ERC: Estimated Remaining Contributio	