



Notes:
The contractors are to check all dimensions, drain runs and general conditions on site before works commence, and inform Akelius immedia upon discovery of any errors, omissions or discrepancies. All works are to be carried out in accordance with current building regul British standards, codes of practice and local authority requirements.

66 & 72 Belsize Lane, London NW3 5BJ

Typical Existing Single glazed Front Window

66BL-10/07/2018 - E 02 Drawn by Checked by A3@1:20 P.M S.A