

THE BRITISH MUSEUM

HVM SECURITY OPTIONS

MONTAGUE PLACE | 11TH OCTOBER 2016

DRAFT

CONTENTS

1.0 Context & Site Analysis	5
2.0 Design Options	13
2.1 Option A1	14
2.2 Option A2	15
2.3 Option A3	16
2.4 Option B	17
2.5 Option C	22
2.6 Option D	27
2.7 Option E	32
2.8 Option F	37



SECTION 1

SITE CONTEXT & ANALYSIS


1.1 CONTEXT | AREA CONTEXT

CONTEXT:


- Located within the London Borough of Camden
- Within the Bloomsbury conservation area
- 6.7 million annual visitors
- North West entrance is the museum's secondary entrance
- Montague place accommodates 50 plus coaches per day within designated laybys
- Upwards of 5,000 people would require emergency egress at this location




1.2 SITE ANALYSIS | SITE CONTEXT



Visitor entrance numbers



Post 2016 Access & Entrance to the Museum (Via Bag Check)



Future Aspirations

- BAG CHECK
- BRITISH MUSEUM MASTERPLAN SITE BOUNDARY
- UOL MASTERPLAN SITE BOUNDARY
- MONTAGUE PLACE.
AREA OF MUTUAL PUBLIC REALM INTEREST
OVERLAPPING UOL & BM MASTERPLAN BOUNDARIES

1.3 CONTEXT | MONTAGUE PLACE / NORTHERN ENTRANCE 2015




Views of Montague Place following streetscape enhancement carried out in 2009 and prior to temporary security / HVM measures installed in 2016

1.4 CONTEXT | TEMPORARY HVM INSTALLATION





1.5 CONTEXT | SITE CONSTRAINTS PLAN



- SITE BOUNDARY
- BASEMENT
- BAG CHECK STRUCTURE
TEMPORARY RAMP
- WATER
- WATER TRUNK MAIN
- SEWER -COMBINED
- GAS MAIN
- FIRE HYDRANT
- DRAIN
- AIR VENT
- EXISTING MATURE TREES & ROOT ZONE

1.6 SITE ANALYSIS | SECURITY CONSTRAINTS PLAN



Minimum Security Bollard Requirement

