



Level and Crack Monitoring



Date of Issue: 05/11/2018

Provider Details

CET Property Services

Monitoring Details

Instruction Date:	04/01/2018		
Number of visits	6	Visit Frequency (Wks)	8

Visit Dates (future dates are estimated)

Setup	1	2	3	4	5	6
13/02/18	10/04/18	05/06/18	31/07/18	25/09/18	20/11/18	15/01/19

Client Details

Insurance Co.:	
Client Ref:	
Client Name:	Sedgwick
Technical Mgr:	Yiu-Shan Wong
Customer support	Sabrina Wood
Tel:	
Email:	


Risk Address

Occupier:	
Address:	Cleve Road
Address:	
Town:	London
County:	
Post Code:	NW6 3RN
Contact Name	

Level and Crack Monitoring - Site Sketch



Date of Issue: 05/11/2018





Level Monitoring - Reduced Levels (in metres)

Our Ref: [REDACTED] Date of Issue: 05/11/18

Reading Date	13/2/18	10/4/18	25/5/18	9/7/18	5/9/18	5/11/18						
Point / Reading	1	2	3	4	5	6	7	8	9	10	11	12
1	10.5164	10.5162	10.5157	10.5146	10.5153	10.5162						
2	10.2114	10.2126	10.2130	10.2113	10.2094	10.2098						
3	10.2156	10.2168	10.2176	10.2158	10.2139	10.2141						
4	10.4931	10.4930	10.4925	10.4917	10.4915	10.4924						
5	10.5226	10.5228	10.5222	10.5210	10.5211	10.5222						
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Not used												
Tech Initials	AL	AJZ	AJZ	AJZ	AJZ	EM						
Level S/N.	521817	521817	521817	AJZ	AJZ	520238						

[REDACTED]	Client Name	Issue Date
	Sedgwick	05/11/2018

Crack Monitoring - Movement Against Time

