



# Air Quality (PM10) Monitoring Report - Baseline

Monitoring Period: 27<sup>th</sup> September to 28<sup>th</sup> October 2018

Client: 8 Build Limited

**Project:** Stephenson House, 75 Hampstead Road, London

**Document Ref.:** EEMC-AQMR-097/001- Stephenson House Rev00



# Air Quality (PM10) Monitoring Report - Baseline

Monitoring Period: 27th September to 28th October 2018

Project No. EEMC/097/2018

Report No. EEMC-AQMR-097/001- Stephenson House Rev00

Client: 8Build Limited

Title: EEMC/097/001 – Stephenson House

Air Quality (PM10) Monitoring - Baseline

Report No.01

Monitoring Period: 27<sup>th</sup> September – 28<sup>th</sup> October 2018

### **Details of Air Quality (PM10) Monitors**

ID Reference	RP1
Location:	2 <sup>nd</sup> Floor Balcony of Stephenson House facing Hampstead Road (East)
Instrument:	TSI DustTrak II (PM10)
Serial Number:	8542183401
Manufacturers last calibration date:	21/08/2018 (Copy of Calibration Certificate in Appendix 1)
Installation Date:	27/09/2018
ID Reference	RP2
Location:	and a second sec
Location.	2 <sup>nd</sup> Floor Balcony of Stephenson House facing Drummond Street (South)
Instrument:	2 <sup>nd</sup> Floor Balcony of Stephenson House facing Drummond Street (South)   TSI DustTrak II (PM10)
Instrument:	TSI DustTrak II (PM10)

Author:	Reviewer:
M. Rebisson	STER
Matthew Robinson BSc (Hons) MIOA Senior Consultant Date: 02/11/2018	lan Hooper MSc IEng MIOA Principal Consultant  Date: 02/11/2018

#### (EEMC) Limited Contact Information:

European Environmental Monitoring & Consultancy (EEMC) Ltd. Suite 31

Chessington Business Centre Chessington, Surrey KT9 1SD

m: 07868 024 786 e: info@eemc.london w: www.eemc.london

(EEMC) Limited have prepared this document for the sole use of the client, using all reasonable skill and care, for the intended purpose(s) and within the resources made available and agreed with the client. No responsibility is accepted for matters outside the terms and scope of the agreement under which this document has been prepared. Similarly, no responsibility in any form is accepted for third party use of this report or parts thereof, the contents of which are confidential to the client. No other warranty, expressed or implied, is made as to the professional advice included in this report.

#### 1.0 Introduction

European Environmental Monitoring and Consultancy (EEMC) Limited have been appointed by 8Build Limited to undertake the monitoring of baseline for air quality (PM10) prior to commencement of demolition and construction works at Stephenson House, 75 Hampstead Road. The Stephenson Road project is in the London Borough of Camden and is bounded by Hampstead Road to the east and Drummond Street to the south.

This report presents the measured and recorded unattended baseline air quality (PM10) monitoring data for the period 27<sup>th</sup> September to 28<sup>th</sup> October 2018.

#### 2.0 Context

The purpose of the air quality (PM10) monitoring works are is to show compliance with and to discharge planning condition 30 as set out in the Camden decision notice below, planning ref: **2017/3518/P** 

"Air quality monitoring should be implemented on site. No development shall take place until full details of the air quality monitors have been submitted to and approved by the local planning authority in writing. Such details shall include the location, number and specification of the monitors, including evidence of the fact that they have been installed in line with guidance outlined in the GLA's Control of Dust and Emissions during Construction and Demolition Supplementary Planning Guidance and have been in place for 3 months prior to the proposed implementation date. The monitors shall be retained and maintained on site for the duration of the development in accordance with the details thus approved.

Reason: To safeguard the amenities of the adjoining premises and the area generally in accordance with the requirements of policies A1, CC1, CC2 and CC3 of the Camden Local Plan 2017."

The Air Quality Assessment (AQA) carried out at the planning stage determined a summary of Impact Risks as set out below:

Stage	Impact Risk		
Stage	Nuisance Dust	Ecology	PM10
Demolition	Medium Risk	Negligible	Low Risk
Earthworks	Negligible	Negligible	Negligible
Construction	Medium Risk	Negligible	Low Risk
Trackout	Low Risk	Negligible	Negligible

The AQA also provides the following guidance:

"Overall, the development is considered to be Medium Risk for nuisance dust soiling effects and Low Risk for PM10 health effects, in the absence of mitigation."

Guidance and policy is set out in the IAQM "Guidance on Air Quality Monitoring in the Vicinity of Demolition and Construction Sites" 2012, and the Mayor of London, Supplementary Planning Guidance "THE CONTROL OF DUST AND EMISSIONS DURING CONSTRUCTION AND DEMOLITION SPG" July 2014. For Medium Risk sites "a minimum of two automatic particulate monitors to measure PM10 levels" are required and that "it will normally be necessary to undertake baseline monitoring for a minimum period of three months".

8Build will carry out their site operations in compliance with the applicable guidance and where possible implementing the mitigation measures outlined in the AQA.

The proposed PM10 trigger and action levels for PM10 concentrations in 15minute mean periods during the works are set out below and are based on the Mayor of London SPG and IAQM guidance mentioned above.



- Trigger Level: 150micrograms/m-3 (150μg/m³)
- Action level: 250micrograms/m-3 (250µg/m³)

Site operations are limited to 08:00-18:00 hours Monday to Friday and 08:00-13:00 on Saturdays.

**Note:** It may be necessary to reassess these limits in the light of new and updated guidance, which suggests an Action Levels of 190 micrograms/m-3 (150 $\mu$ g/m-3) over a 1hr mean may recommended. (IAQM Guidance Oct 2018 v1.1)

#### 3.0 Instrumentation

Two TSI Dust Trak II (PM10) Monitors have been deployed to undertake baseline unattended monitoring (PM10). A map showing the location of the monitors is show in in Figure 1. Photographs showing the equipment installed at locations RP1 and RP2 are shown in Image 1 and Image 2 below.

The monitors were installed on site on Thursday 27<sup>th</sup> September 2018.

The monitors are housed in weather-resistant environmental enclosures and installed at elevations agreed between 8 Build and the London Borough of Camden. Each system is fitted with a modem to allow remote access to measurement data on the internet. The monitors record PM10 ( $\mu g/m^3$ ) contiguously over 15-minute average periods.

The Monitor installed are as below:


- RP1 TSI Dust Trak II (PM10) MCerts approved light scatter nephelometer, serial no. 8542183401
- RP2 TSI Dust Trak II (PM10) MCerts approved light scatter nephelometer, serial no. 8542183404

A copy of the calibration certificates are attached in Appendix 1.


#### 4.0 Measurement Results

The results of the air quality (PM10) measurements are presented graphically in Section 4.1 below.

**Figure 1: Map of Monitor Locations:** 




## **Image 1: Photograph of RP1 Monitor:**





## **Image 2: Photograph of RP2 Monitor:**





### 4.2 Air Quality (PM10) Monitoring Graphs













## 4.2 Summary of Air Quality (PM10) - 24 hour Average

A summary of measurement data at RP1 and RP2 shown as 24 hour average values is summarised below in Table 1:

Date	RP1 (μg/m³)	RP2 (μg/m³)
27/09/2018	9.9	10.6
28/09/2018	7.0	6.9
29/09/2018	11.0	11.0
30/09/2018	10.3	10.5
01/10/2018	4.7	4.7
02/10/2018	4.9	5.2
03/10/2018	6.1	6.4
04/10/2018	13.5	13.8
05/10/2018	20.3	20.5
06/10/2018	10.8	10.5
07/10/2018	5.0	5.2
08/10/2018	7.9	8.5
09/10/2018	10.3	11.1
10/10/2018	43.3	42.5
11/10/2018	11.8	11.7
12/10/2018	6.6	7.3
13/10/2018	7.6	8.0
14/10/2018	3.1	3.1
15/10/2018	8.9	8.8
16/10/2018	17.3	17.4
17/10/2018	10.0	10.1
18/10/2018	11.2	11.1
19/10/2018	13.1	12.7
20/10/2018	27.9	28.0
21/10/2018	18.5	18.4
22/10/2018	7.9	7.7
23/10/2018	9.1	9.2
24/10/2018	9.7	9.6
25/10/2018	13.8	13.7
26/10/2018	4.9	4.9
27/10/2018	3.7	3.4
28/10/2018	3.9	3.9
Daily Mean	11.1	11.1

Table 1 – Summary of 24-hour averages



#### 5.0 Discussion & Summary

Unattended baseline air quality (PM10) monitoring has been undertaken at Stephenson House project, prior to commencement of demolition and construction works.

This report presents the measured and recorded air quality (PM10) concentrations measured and recorded at monitoring positions RP1 and RP2 from 27<sup>th</sup> September to 28<sup>th</sup> October 2018. The data provides the ambient baseline PM10 levels at each location.

PM10 concentrations during this period are below the proposed Trigger and Action levels.

PM10 data from the London Air Quality Network (LAQN) is available for public access. The nearest measurement locations to Stephenson House are shown below, with the average daily (24 hour) mean PM10 concentration in ug/m³ between 01-Sep-2018 and 01-Nov-2018.


Site Code	Site Name	Result (μg/m³)
CD1	Camden – Swiss Cottage	17.6
CD9	Camden – Euston Road	21.2
MY7	Westminster – Marylebone Road FDMS	22.1

This data is supplied by the LAQN with the following caveats.

- Warning: Camden Euston Road Warning: Calculation included provisional data. Data after 16 Feb 2018 have not been fully ratified.
- Warning: Camden Swiss Cottage Warning: Calculation included provisional data. Data after 31 Dec 2017 have not been fully ratified.
- Warning: Westminster Marylebone Road FDMS Warning: Calculation included provisional data. Data after 31 Dec 2017 have not been fully ratified.



Appendix 1 – Copy of Calibration Certificate





## RP2 Unit - TSI DustTrak II (PM10) 8542183404:

