



### Geotechnical Testing Analysis Report



environmental +  
claims mgmt +  
subsidence +  
drainage +



#### Summary Of Claim Details

<b>Policy Holder</b>	[Redacted]
<b>Risk Address</b>	23 Laurier Road London NW5 1SH
<b>SI Date</b>	27/09/2018
<b>Issue Date</b>	28/09/2018
<b>Report Date</b>	15/10/2018
<b>Auger Reference</b>	[Redacted]
<b>Insurance Company</b>	Legal & General Insurance
<b>LA Claim Reference</b>	[Redacted]
<b>LA Co. Reference</b>	Cunningham, Lindsey

This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.

	Checked	15/10/2018	Wayne Honey	[Redacted]
	Approved	15/10/2018	Ben Sharp	[Redacted]





### Oedometer Results

Borehole No: 1				
Location 23 Laurier Road London NW5 1SH				
Depth (m)	Sample No & Comments	Moisture Content %	STRAIN	Dd (mm)
1.10		29	0.0402	80.45
2.10		34	0.0141	28.15
				108.60

Total Column Dd : 108.60 mm Therefore Free Surface Heave Potential Over B/H is about 0cm to 11cm

Borehole No: 2				
Location 23 Laurier Road London NW5 1SH				
Depth (m)	Sample No & Comments	Moisture Content %	STRAIN	Dd (mm)
1.50		21	-0.0331	-66.10
2.50		28	0.0456	91.20
				25.10

Total Column Dd : 25.10 mm Therefore Free Surface Heave Potential Over B/H is about 0cm to 25cm



23 Laurier Road London NW5 1SH

