

**Brierfield Community Hall, Arlington Road, London NW1 7LG**

PHOTOS AS EXISTING



Brierfield from Arlington Road – community hall in basement at right-hand end of block



East elevation detail, with gate giving access to Community Hall on left





Existing entrance door and glazed screen (painted) from steps down



Entrance steps and wheelchair ramp (to be replaced by external platform lift)





View from garden looking eastwards, with glazed door + screen to entrance lobby (to be infilled)



View towards window in west elevation (garden overgrown)



Community hall looking eastwards – high level window obscured by refuse bins



Entrance hall from rear garden looking towards entrance door





Community hall, looking south west – boiler + kitchen fittings removed, frosted glass to windows



View from entrance hall towards garden