Your ref: 2019/0231/P

Our ref: 1814



**Dear Matthias** 

## RE: 71 A Broomsleigh Street London NW6 1QQ

Following on from our meeting on site, as discussed please find below additional information to support the application.

## Site Photographs



Front of the property, showing the combination of materials used in windows in the immediate vicinity of the property



Poor quality white painted brickwork to rear and side walls to be improved. Window to the rear proposed to be centralised and pipework to side wall rationalised.









Poor quality white painted brickwork to rear and side walls to be improved. Pipework to side wall to be rationalised



Damaged forecourt wall



Yours Sincerely

Laura Thompson Architect

Sketch Plan Build Architecture Ltd