


1557-P1E-1: Belmont Street, London RISNER DESIGN Ltd



1557-P1E-1: Belmont Street, London RISNER DESIGN Ltd



Appendix G - Owner's Questionnaire

Questionnaire, for completion by current or previous owner or manager, please enter Not Known where you are unable to provide an answer.

1 Belmont Street, London NW1 8HJ

I have managed the above site from 01/12/18 to present (as contractor carrying out refurbishment works)

Existing site & property details:

Site use:	Vacant at present but was previously a motor bike repair shop	
Number of Buildings:	1 ground floor and basement unit	
Building 'A', Nature of Use: (insert lines as required)	B1© light industrial	
Date of Construction	Victorian	
Land Area (ha):	Footprint of basement 45 sqm	
Current Tenants:	Vacant at present	
Any asbestos containing materials?	None. Just had an asbestos report completed	
Asbestos Survey available?	Yes. Will send on with the email.	
Any archaeological, geotechnical or environmental reports?	None	

Current site utilities:

Commercial/Household Waste Disposal	
Sewage Discharge and Disposal	To main drain
Surface Water Drainage	To main drain
Source of heating and cooling	At present electric only with no gas connection. Propose to have a new gas connection installed in the new design with underfloor heating in basement and heat recovery mechanical ventilation.
Wells?	No
Septic System?	No

Historical site activities (if answered 'yes', please provide details):


Are you aware of any other past use of the site?	No. There are residential flats above in the same building though on the 1 st and 2 nd floor
Are you aware of any other past use of adjacent areas?	No
Has anything been buried on or within 250m of the site?	Not that I know of
Have any chemicals been stored on or within 250m of the site?	No that I know of
Have any potentially contaminating processes been undertaken either on or within 250m of the site?	Motor bike repairs. I think the planners were concerned at potential of motor bike oil leaking onto the slab.
Has there been any oil or fuel storage on or within 250m of the site?	Yes. As described above.
Has any fill material been deposited on or within 250m of the site?	No that I know of
Have any animals been kept on site?	No

Signed:

Date: 28/01/2019 Name: Mark Risner Company:RisnerDesign



Appendix H - Vapour sample location



1557-P1E-1: Belmont Street, London RISNER DESIGN Ltd



Appendix I - Contacts

Local Authority	Building Control	020 7974 6941
Local Authority	Environmental Health	020 7974 4444
	National Customer	08708 506 506
Environment Agency	Contact Centre	
	PO Box 544	enquiries@environment-
	Rotherham	agency.gov.uk
	S60 1BY	
	Mining Reports Office	
Coal Authority	200 Lichfield Lane	www.coalminingreports
	Berry Hill, Mansfield	<u>.co.uk</u>
	Notts, HG18 4RG	
Health Protection	Chilton	01235 822622
Agency, Radiation	Didcot	radon@hpa.org.uk
Protection Division	Oxon, OX11 oRQ	www.hpa.org.uk/radiation