

**CRASH MAP - AROUND ST CRISPIN'S CLOSE**  
 All types over the past 20 years




Figure 1: The immediate area

Only three incidents are recorded as having occurred within the past twenty years near the Close, suggesting that the area is relatively safe from a highways perspective. The fact that only one vehicle was involved in every instance points to isolated driver error, not collision.



Figure 2: Wider area

In comparison, the wider area has a far greater concentration of incidents. St Crispin's Close (towards the top of the image) has far fewer than the surrounding vicinity.