

**VIEWS ALONG THE HIGHWAY**

South End Road towards St Crispin's Close



Figure 1: View heading north

The entrance to St Crispin's Close is clearly visible up on the right. There is a pelican crossing, and traffic calming measures such as reflective bollards. There are also frequently staged street lights and a wide central reservation in the road.



Figure 2: View north - from further

The view north from further back. Further traffic calming measures (pedestrian islands and bollards). Note the 20 mph sign.



Figure 3: View heading south

The entrance is clearly visible owing to the wide pavement, which provides clear visibility splays. Not the traffic bollards immediately opposite the entrance and the regularly spaced streetlights. In the immediate foreground are road markings showing the pelican crossing (from where this image was taken). Further evidence of crime is to be seen in the single bike wheel left chained to the bike rack to the left (following, presumably, the theft of the rest of the bike).