

GROUND FLOOR PLAN

This survey is of a preliminary nature. The trees were inspected from the ground only on the basis of the Visual Tree Assessment method. No samples were taken for analysis. No decay detection equipment was employed. The survey does not cover the arrangements that may be required in connection with the laying or removal of underground services.

Branch spread in metres is taken at the four cardinal points to derive an accurate representation of the crown.

Root Protection Areas (RPA) are derived from stem diameter measured at 1.5 m above adjacent ground level (taken on sloping ground on the upslope side of the tree



Landmark Trees

Tel: 0207 851 4544 Mobile: 07812 989928 e-mail: info@landmarktrees.co.uk Web: www.landmarktrees.co.uk

Site:49 Belsize Lane Drawing Title: Tree Constraints Plan April 2019

Category A
High Quality

Category B
Moderate Quality Category C Low Quality

Root Protection -

Category -

Category U
Trees Unsuitable for Retention

- Species Tree Position Approximate (not shown on original survey)

- Crown Spread

- Tree Number