

- Existing windows removed to be blocked up to allow for abutment of new enclosure.
- Existing services and plant stripped out of lightwells.
- Existing roof structure to existing plant space removed.
- Existing 1990's conservatory removed.
- Existing drainage pipework to be stripped out. Sections of pipework assumed to be original.
- Existing services and plant stripped out of lightwells.
- Bottom three courses of slate to be removed, repaired and reinstated.
- Rooflights to lanterns over Council Chamber removed.
- Windows to upstands of lanterns removed.
- Doors onto lightwells removed to allow for replacement with automatic opening replacement for smoke ventilation.
- Openings created in façade at each floor level to provide access into lightwell, serving as new lift lobby.
- Non original windows to be removed in order to insert new windows into openings to match original.



**Notes:**

Drawings are based on survey data and may not accurately represent what is physically present.

All dimensions are to be verified on site before proceeding with the work.

All dimensions are in millimeters unless noted otherwise.

Purcell shall be notified in writing of any discrepancies.



#### Demolitions & Alterations Key

Original fabric defined as that documented in Archive Drawings. Where date of fabric is unknown, it is assumed as original.


- Original Fabric: Section of Wall/Slab to be Demolished
- Original Fabric: Item to be Demolished
- Overhead - 300mm wide opening to ceiling for high level concealed cable distribution - make good after installation
- Overhead: Whole bay of vaulted ceiling to be removed for cabling distribution and reinstated
- Original Fabric: High level opening in wall for services distribution
- Floor trenches in slab for cable distribution
- Manhole: Opening in slab
- Non-Original Fabric: Section of Wall to be Demolished
- Non-Original Fabric: Item to be Demolished

- Window Number
- Door Number
- Annotation Item

Drawings to be read in conjunction with:

Internal Repairs & Builder's Works drawing series (93)000 for key spaces

Conservation Strategy Report: CTH-PUR-MP-00-SP-A-00005




S5 P00 18 Apr 2019 08 NS

ISSUE	DATE	DRAWN	CHECKED	DESCRIPTION
<b>DRAWING TITLE</b>	GA PROPOSED DEMOLITIONS AND STRIP OUT SOUTH-EAST LW.04 - ELEVATIONS			
<b>DRAWING NO.</b>	CTH-PUR-MP-ZZ-DR-A-91107			
<b>REVISION</b>	S5 P00			
<b>SIZE &amp; SCALE</b>	A1L 1:200			
<b>DRAWING STATUS</b>	S5 SUITABLE FOR PLANNING			

**CLIENT** Lendlease

**PROJECT** Camden Town Hall

**JOB NUMBER** 238664



15 Bermondsey Square, Tower Bridge Road, London, SE1 3UN | T: +44(0)20 7397 7171, E: london@purcelluk.com  
© PURCELL 2012. PURCELL ® IS THE TRADING NAME OF PURCELL MILLER TRITTON LLP

**1 LIGHTWELL 4 - NORTH ELEVATION**  
**91107 1:200 @ A1**

**2 LIGHTWELL 4 - EAST ELEVATION**  
**91107 1:200 @ A1**

**3 LIGHTWELL 4 - SOUTH ELEVATION**  
**91107 1:200 @ A1**

**4 LIGHTWELL 4 - WEST ELEVATION**  
**91107 1:200 @ A1**