Application No:	Consultees Name:	Received:	Comment:	Response:	Printed on:	08/05/2019	09:10:04
2019/1875/L	Eton CAAC	27/04/2019 17:16:31		Eton Conservation Area Advisory Committee			
				Advice from Eton Conservation Area Advisory Committee: 26.04.2019 Re: 1 Provost Road, 2019/1875/L			
				Re-siting of alarm boxes on side and rear elevations This is the second time that we have commented on a listed building application for alarm bell boxes. The first occasion was in December 2018 in respect of 2 Provost R it may have been this application which alerted conservation officers to the unauthori bell boxes on Listed buildings in Provost Road. This application seeks to regularise to on the side and rear elevations at 1 Provost Road.	load, and we lised mounting	oelieve that of alarm	
				As we stated in our advice in December 2018, alarm bell boxes are often mounted in from the overall appearance of a building. In Provost Road there are some mounted on the front elevation facing the street which is clearly harmful to the clean, simple st the listed buildings.	in prominent	positions	
				However, it is recognised that alarm bell boxes should be visible so as to provide a d criminals, and this is the advice that is given by Camden's Crime and Safety website burglars think twice". We would like to see them mounted in less visible positions on rather than the front.	- "visible alar	ms make	
				In relation to 1 Provost Road the alarm boxes appear to have been mounted as discrensuring they maintain a degree of visibility.	retely as is po	ssible while	
				We have no objection to this application.			
				Yours sincerely,			
				Eton CAAC			