



| | | |
|-----------|---|--|
| Testing |  | R.P. Testing Solutions Limited <i>Pile and Concrete Testing Specialist</i> |
| Solutions | | |

ON SITE INTEGRITY TEST LOG

| | | | | | | | | | |
|----------------------|---------|------------|--|-----------------------|--|--|--|--|--|
| CLIENT: | Scoband | | | SITE: | | | | | |
| Job No: | | | | 17 HUPPESFIELD NWS | | | | | |
| No: OF PILES TESTED: | 3 | | | | | | | | |
| PILES TESTED AT: | | | | FINAL LEVEL | (CAST LEVEL) | | | | |
| DATE: | 12/6/19 | | | TESTING COMPLETED: |  | | | | |
| PILE NUMBERS: | | | | TESTED BY: Steve | | | | | |
| P01 | | | | | | | | | |
| 2 | | HOUSE | | | | | | | |
| 3 | | 000 321 | | | | | | | |
| | | LOW | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

COMMENTS

The 3 piles tested were of a reliable integrity