



Incursion of wall on T.1  
 Incursion = 0.14m<sup>2</sup>  
 Area available = 6m<sup>2</sup>  
 TOTAL = 2.33%  
 Comments= Insignificant  
 but will require monitoring

**KEY**

- Root Protection Area (RPA)
- Tree Stem
- T1 Tree No.
- Tree Impacts

**Guide To Tree Quality Assessment Categories**

- A
- B
- C
- U

This drawing has been prepared in accordance with BS 5837:2012.

This drawing is intended to be printed and used in colour only, and for no purpose other than the consideration of trees in accordance with BS 5837.

THIS DRAWING IS CONFIDENTIAL AND MUST NOT BE REPRODUCED WITHOUT THE CONSENT OF APEX ENVIRONMENTAL LTD

CLIENT  
Mr A Philips

PROJECT  
AEL-18129  
16 Lyndhurst Gardens  
London NW3 5NR

TITLE  
Tree Impact Plan

DWN	DATE	CHK'D	DATE	APP'D	DATE	SCALE
RJH	10/06/2019					1:100

Apex Environmental Ltd  
 3 Lawrence Way, Lichfield,  
 Staffordshire,  
 WS13 6RD  
 Tel: 0121 249 1235  
 www.ael-treeconsultants.co.uk

Drawing Number  
AEL-18129-TIP

A3  
REV. A

