## MATERIALS LEGEND

Existing painted timber casement windows

Existing plastic gutters & rainwater goods

All dimensions are shown in millimetres unless stated otherwise. The contractor is to check and verify all building and site dimensions, levels and sewer invert levels at connection points before setting out, fabrication or works starting on site. Any discrepancies to be brought to the attention of the architect. If in doubt, ask.

The drawing and the works depicted are the copyright of this practice and may not be reproduced except by written permission Copyright Redworks Ltd. t/a Catterall Franklin.

74 Parkhill Road

Mr Leon N. Ferera

London NW3 2YT

- Existing brickwork boundary walls
- Existing slated roof
- Existing leadwork
- 6. Existing flatroofing
- Painted timber facing boarding



Elevation - Existing

CATTERALL FRANKLIN

Unit 3 Angel Wharf 55 Eagle Wharf Rd London N1 7ER

tel: 020 7193 7818 email: hello@catterallfranklin.com web: www.catterallfranklin.com

27/06/2019

ΑF

1:50 @ A3

EX\_202

1901

Date Drawn Chk