


# ROOT IDENTIFICATION

## for Subsidence Management Services

55 Albert Street, London, NW1 7LX

Client: Subsidence Management Services  
 Client Contact: Robert Kelso  
 Claim Number: [REDACTED]  
 Client Reference: [REDACTED]  
 Policy Holder: Mr Marios Stergides  
 Report Date: 15 February 2019  
 Our Ref: [REDACTED]



Intec

Sub Sample	Species Identified	Root Diameter	Starch
<b>TP/BH1:</b>			
0.8-1.3m	<i>Tilia</i> spp.	3 mm	Abundant
0.8-1.3m	<i>Ficus</i> spp.	1 mm	Absent
1.3-2.3m	<i>Ficus</i> spp.	1	1.5 mm Absent
2.3-3.8m	<i>Tilia</i> spp.	2	1 mm Abundant

**Comments:**

- 1 - Plus 3 others also identified as *Ficus* spp.  
 2 - Plus 4 others also identified as *Tilia* spp.

*Tilia* spp. are limes.  
*Ficus* spp. are figs.

**Signed:** M D Mitchell

Unless we are otherwise instructed in writing, the above sample material will normally be disposed of 6 years after the date of this report.