

Site: 73-75 Avenue Rd

Date: 7th August 2018 amended 30/07/19

## Appendix B

### BS5837:2012 Tree Survey Schedule

Arbortrack Systems Ltd

07986 122074

Surveyor(s): James Bell

Ref: jwmb/rpt1/73-75avenuerd/AIA



Tree No.	English Name	Height	Crown Spread	Ground Clearance	Stem Diameter	Protection Radius	Age Class	Growth Vitality	Structural Condition	B.S. Cat	Sub Cat	Useful Life	Comments
1	Laburnum	8	2/2/1.5/2.5	2	120	1.4	Young	Normal	Good	C	2	20+	Good scope for new boundary treatment on western flank replacing trees 1-5 if necessary.
2	Birch, Silver					0.0							Stump 43cm diameter: flush to ground level
3	Hawthorn, Common	6.5	1.25	2	210	2.5	Semi-mature	Poor	Fair	U		<10	Dying back (uniform)
4	Pittosporum	5	1.5	1.5	135	1.6	Semi-mature	Normal	Good	C	2	20+	Garden ornamental
5	Pittosporum	7	2	1.5	262	3.1	Early Mature	Normal	Good	C	2	20+	Garden ornamental Partially under crown if copper beech in adjoining garden
6	Pittosporum					0.0							Stump 12cm diameter: flush to ground level
7	Beech, Copper	22	8777	3	800 #	9.6	Mature	Normal	Good	A	2	>40	Offsite in adjoining garden Bifurcation @ 5m

Site: 73-75 Avenue Rd

Date: 7th August 2018 amended 30/07/19

## Appendix B

### BS5837:2012 Tree Survey Schedule

Arbortrack Systems Ltd

07986 122074

Surveyor(s): James Bell

Ref: jwmb/rpt1/73-75avenuerd/AIA



Tree No.	English Name	Height	Crown Spread	Ground Clearance	Stem Diameter	Protection Radius	Age Class	Growth Vitality	Structural Condition	B.S. Cat	Sub Cat	Useful Life	Comments
8	Plane, London	26	8/12/8/8	2	1230	14.8	Mature	Normal	Fair	C	2	10+	Large cavity @ base Pollard (Old) Massaria check advised; callused entry wounds @ 8/9m; upgrade to B category subject to Flinv
G9	Lime, Common	15	3	3	400	4.8	Early Mature	Normal	Good	C	2	20+	Suckering from base & topped Screens property to S Height varies between 13m & 15m; SD of 1=400, 2=370, 3=340, 4=420, 5=410, 6=380 & 7=480
10	Yew, Common	7	3.5/1.5/1.5/1.5	0	185	2.2	Semi-mature	Normal	Good	C	2	>40	4 small trees; C is most prominent; SD of a=110 & 110, b=110+90+60+90+50, c=90+50+90+50 & d=120 +100
11	Oak, English	25	5898	4	810	9.7	Mature	Normal	Good	B	2	>40	Entry wounds on trunk Asymmetry (major) Decay pocket @ 3.5m; bifurcation @ 2.3m
12	Maple, Norway	14	3322	2	300	3.6	Early Mature	Normal	Good	C	2	20+	Bifurcation @ 2m Suppressed by neighbours
13	Beech, Common	19	2	2	350	4.2	Early Mature	Normal	Fair	C	2	20+	Poor form Suppressed by neighbours Bifurcation @ 2.3m; poor form with drawn habit
14	Chestnut, Horse	18	9793	5	860	10.3	Mature	Normal	Good	B	2	20+	Bifurcation @ 1.75m Leaf/shoot disorders Powdery mildew; small leaf size; damage to near boundary wall

Site: 73-75 Avenue Rd

Date: 7th August 2018 amended 30/07/19

## Appendix B

### BS5837:2012 Tree Survey Schedule

Arbortrack Systems Ltd

07986 122074

Surveyor(s): James Bell

Ref: jwmb/rpt1/73-75avenuerd/AIA



Tree No.	English Name	Height	Crown Spread	Ground Clearance	Stem Diameter	Protection Radius	Age Class	Growth Vitality	Structural Condition	B.S. Cat	Sub Cat	Useful Life	Comments
15	Pear	8	2532	1.5	300	3.6	Early Mature	Normal	Fair	C	2	10+	Heavily suppressed by tree 14
16	Yew, Common	5.5	3424	0	150	1.8	Young	Normal	Good	C	2	>40	
17	Elder	5.5	2332	1.5	213	2.6	Mature	Normal	Good	C	2	10+	
18	Chestnut, Red	14	4574	2	760	9.1	Mature	Normal	Fair	C	2	10+	Bifurcation between 2-3m Leaf/shoot disorders & canker Heavily reduced; powdery mildew; deadwood in upper crown & extensive canker; end weighted to SE over road; borderline U category
19	Chestnut, Red	14	3.5/3/6/4	2	620	7.4	Mature	Normal	Fair	U		<10	Canker Heavily reduced Minor deadwood; extensive decay @ trunk base: ganoderma; dead/dying as of recent survey
20	Lime, Common	22	5.5/7/7/75	2.5	750 #	9.0	Mature	Normal	Fair	B	2	20+	Trunk grown onto/around wall Reduced to 14m in past Asymmetric trunk: not possible to measure SD accurately; trunk is pushing wall out
21	Chestnut, Red	13	5365	2	550	6.6	Mature	Normal	Fair	B	2	20+	Crown over road Marginal B/C category Close to wall: could be damaging it already

Site: 73-75 Avenue Rd

Date: 7th August 2018 amended 30/07/19

## Appendix B

### BS5837:2012 Tree Survey Schedule

Arbortrack Systems Ltd

07986 122074

Surveyor(s): James Bell

Ref: jwmb/rpt1/73-75avenuerd/AIA



Tree No.	English Name	Height	Crown Spread	Ground Clearance	Stem Diameter	Protection Radius	Age Class	Growth Vitality	Structural Condition	B.S. Cat	Sub Cat	Useful Life	Comments
22	Chestnut, Red	16	4.3/5/5/5	2	410	4.9	Early Mature	Normal	Good	B	2	20+	Minor fluxing on trunk Pruning wounds @ 2m & 2.5m
23	Magnolia (M. X soulangiana)	4.5	1.5/1.5/2/2.5	2	70	0.8	Young	Normal	Good	C	2	20+	Garden ornamental Removed
24	Chestnut, Horse	18	6575	2	630	7.6	Mature	Normal	Good	B	2	20+	Cable braced:branches over rd Topped Mid crown PBC symptoms; included bark unions
25	Chestnut, Red					0.0							2.5m stump SD = 62cm
26	Plane, London	24	8877	9	1270	15.2	Mature	Normal	Good	A	2	>40	Pollard (Old) 28 on scan On frontage of neighbouring property
27	Plane, London	24	14/12/8/8	5	1116	13.4	Mature	Normal	Good	A	2	>40	Pollard (Old) 29 on scan Street tree; Massaria stub to SSW @ 9m
28	Plane, London	20	10/9/9/6	5	890	10.7	Mature	Normal	Good	B	2	>40	Pollard (Old) 30 on scan Street tree